

EXISTING INFRASTRUCTURE REVIEW

1. Drainage & Culvert Review

The existing stormwater infrastructure within the Summer Village is mainly a rural drainage system comprised of open ditches, swales and culverts. There are no underground sewer systems or curb and gutter flow systems presently. There are also areas of undeveloped lands which contain undisturbed natural flow.

The age of the existing infrastructure appears to vary from recent to +50-year-old installations. Culverts along Sunset Drive are more aged than areas upland. Lot approach culverts comprise mainly of 300mm diameter corrugated steel pipes (c.s.p.) and road centerline culverts vary from 500 – 800mm diameter corrugated steel pipes (c.s.p.).

Existing culverts do not include sloped ends or meet current standards for rip rap placement. Most ditches exhibit well grassed flow areas with relatively low to flat grades.

2. Scope of Review

The scope of review for this report is intended to identify issues with the current drainage system through the Summer Village regarding the following:

- Sufficient capacity of flow for a 1 in 25-year precipitation event.
- Proper flow direction that meets the overall drainage plan for the Summer Village.
- Prevents flooding or increase flow rate into adjacent lots.
- Culvert condition.
- Erosion and scour due to drainage.
- Road failures caused by culvert failures.
- Major outfalls into lakes and watercourses.

Upon inspection, the report will:

- Determine replacement and improvement requirements.
- Develop a rating system to quantify the condition of the infrastructure.
- Determine costs of replacements and improvements.
- Provide a scheduled program for these replacements and improvements.

3. Culvert Standards

The design life cycle of C.S.P. culverts are usually in the range of 50 to 75 years. Some may last longer than 75 years, however this is often due to budgeting constraints or culverts that have little to no drainage associated with it.

One of the first strategies to focus on will be to upgrade the minimum size standards of culverts in the Summer Village. Setting a minimum size standard is important as it will provide consistency as well allowing for an ensured flow capacity. It also allows a certain level of accessibility for maintenance such as flushing out silt and/or debris.

Previously, lot approaches used a minimum of 300mm diameter sized culvert. It is desirable to increase this minimum size to 500mm diameter. The following changes in standards is proposed:

	<u>Previous Min.</u>	<u>Proposed Min.</u>
Lot Approach Culverts:	300mm Dia.	500mm Dia.
Road Centerline Culverts:	500mm Dia.	600mm Dia.
Major Flow Culverts:	500mm Dia.	800mm Dia. or 2 – 600mm Dia.
Long Culverts (>20m):		600mm Dia.

Overall, larger diameter culverts require less maintenance and provide better flow dynamics. When considering a replacement program, a cost benefit analysis will indicate that slightly oversizing culverts will always provide better return over the life cycle of the culvert.

4. Inspection

A thorough inspection was completed of the Summer Village's drainage paths and culvert infrastructure. A GPS survey was completed for each culvert providing position, elevation, slope and length. The culverts were inspected for condition, inlet/outlet adequacy and surrounding affects. Photos of the culvert inlet, outlet and inside barrel were taken.

All the inspection survey, notes and photos were compiled onto individual "Culvert Inspection Reports". Each culvert was given a culvert number and drainage flow name.

In summary, a full inventory of the Summer Village's culverts was prepared and documented. See Appendices for these reports.

5. Culvert Rating System

A Culvert Rating System was developed for this Infrastructure review. A rating system was necessary to determine and categorize the priority of improvements and replacements. The rating of a culvert is based on a 26-point system, where a low score indicates that the culvert is in good condition and will not require replacement for many years. A high score indicates that there are substantial concerns with the culvert and some form of improvement or rehabilitation is needed. Even though the maximum score for any culvert is 26, scores generally 10 and above are considered important and likely should be addressed within a 5-year action plan.

Each culvert was given a unique number along with a unique drainage flow name. Numbers are shown as a 2000 series number. Drainage flow names comprise of an alphabet followed by a number.

The Rating System comprises of four main areas:

- Minimum Diameter Compliance
- Flow Capacity
- Affect on Roadway/Approach
- Barrel Condition
- Inlet/Outlet Characteristics

Each of these areas contains a scoring system as follows:

5.1 Minimum Diameter Compliance

For Centreline Culverts, the culvert needs to be at least 600mm diameter. If not, 1 point is added to rating score.

For Approach Culverts, the culvert needs to be at least 500mm diameter. If not, 1 point is added to rating score.

5.2 Capacity

Culvert Capacities for each culvert location are shown on the "Outlet Flow Paths" Drawings and are categorized as follows:

- Negligible Flow
- Inadequate
- 5 – Year
- 10 – Year

- 25 – Year - This is the design target for the Summer Village
- 100 – Year

The above basically refers to the amount of capacity each culvert has based on the storm modelling of a 5-year to 100-year storm. It should be noted that the capacities are significantly affected by the slope of the culvert since the modelling takes into account the velocity of flow and where restrictions or slowing of flow may occur. The design target used for culverts for the Summer village is a 25-Year storm.

For the rating of culvert capacity, the following scoring was used:

Major Flow Path:	If yes,	add 2 points
Contains Negligible Flow:	If yes,	add 0 points
Contains 25-Year Storm Capacity:	If yes,	add 0 points
Contains 10-Year Storm Capacity:	If yes,	add 1 point
Contains 5-Year Storm Capacity:	If yes,	add 2 points
Contains Inadequate Capacity:	If yes,	add 3 points
Contains Emergency or Caused Past Flooding:	If yes,	add 6 points

Culvert capacity is considered very important in maintaining drainage within the community and hence has the highest potential for adding points to the rating.

5.3 Roadway

This component considers the effects that a culvert may have on other crucial infrastructure elements such as roadways and accesses. In this case, the road condition over the culvert is important since a road closure is not feasible. For this reason, the following items have a high score associated with them:

Contains Severe Cracking due to Sub-Structure:	If yes,	add 3 points
Contains Severe Pot-Holing due to Sub-Structure:	If yes,	add 3 points
Contains Severe Sag/Dip in Road due to Sub-Structure:	If yes,	add 3 points

5.4 Pipe Barrel

This area evaluates the culvert itself in its performance, stability and overall life. Since any type of structure failure of a culvert will lead to imminent failure, the following items have a moderate score associated with each:

Sag or Bowing of the pipe:	If yes,	add 2 points
Out of Round or Caving In:	If yes,	add 2 points
Settlement of the base:	If yes,	add 2 points
Infiltration of water/cracking/joint separation:	If yes,	add 2 points

Severe Corrosion:	If yes,	add 2 points
Moderate Corrosion:	If yes,	add 1 point
Blockage, partial (>50%) or full:	If yes,	add 2 points

5.5 Inlet / Outlet

For inlet and outlet areas of the culvert, the following aspects are inspected and rated as follows:

Inlet/Outlet Damage:	If yes,	add 1 point
No Sloped Ends:	If yes,	add 1 point
Sediment Build Up:	If yes,	add 1 point
Erosion above the Pipe:	If yes,	add 1 point
Scour below the Pipe:	If yes,	add 1 point
Needs Rip Rap:	If yes,	add 1 point
Needs Clearing of Trees/Brush:	If yes,	add 1 point
Needs De-Vegetation at Inverts (disrupts flow):	If yes,	add 1 point

6. Cost Estimates

Cost of improvements and replacements of culverts and drainage systems have been calculated, with some detail, and included within this report. It is important to note that these are preliminary estimates and need further detailed design to better quantify the costs. Also, all costs are calculated to present day values using construction unit prices based on 2017 – 2019 averages. Adjustments for inflation and price fluctuations will be required for all work past 2020. Land acquisition costs, utility relocation costs and traffic accommodation costs, if required, are not included. Drainage improvements to ditches, if necessary, are also not shown (e.g. lowering or widening of ditches).

7. Improvement Strategy

In order to provide a plan for future improvements, it is necessary to use the rating system defined above to determine priorities over a period of time.

The strategy and timing for improvements and rehabilitation is proposed in the following order of priority:

- Emergency Measures and/or Prevention of Past Flooding Events
- Improvements to Re-Direct Flow Paths

- Improvements to Major Flow Paths
- Infrastructure with Remaining Life of <5 Years
- Improvements to Minor Flow Paths
- Rehabilitation/Replacement Program for Centerline Culverts
- Rehabilitation/Replacement Program for Approach Culverts

8. Improvement, Rehabilitation & Maintenance Programming

Due to funding constraints and the timing of when a culvert has reached its design life, it is important to develop an improvement, rehabilitation and maintenance program for the Summer Village.

Using the rating system, the urgency and priority of work required becomes very evident. The order of work is therefore summarized below and is detailed within the Appendices:

List of Major Improvement Projects

Priority #1: **PROJECT #1: Old Railway Embankment & 48A Avenue Drainage Improvements**

Remove existing culverts within the Old Railway Embankment. Construct Drainage Swale/Channel along east side of the embankment, 300m north of 48A Avenue and 300 - 400m south of 48A Avenue. Install a new 800mm Dia. C.S.P. at 48A Avenue to drain the collected flow to cross under the Old Railway Embankment.

Along 48A Avenue and Sunset Drive, Flow Path D will be upgraded by lowering the ditch profile to the lake and culverts under approaches and roads increased in size to ensure unrestricted flow.

Regrading of the ditch along the west side of the Old Railway Embankment, 400m north of 48A Avenue, will also be completed in order to ensure positive flow to 48A Avenue. The ditch will also be re-shaped to construct a higher backslope to restrict flow to the ditch and not into the back of lots.

Recommended Time of Work: 2020 – 2021

Priority #2: **Blocked Culverts, Missing Culverts**

Rehabilitation or improvement to blocked/plugged/ culverts or locations needing culverts that restrict flow.

Recommended Time of Work: 2020 - 2022

Priority #3: **PROJECT #2: Central Drainage Way for the 49A Avenue & 48th Street Area**

Phase 1: Obtain 20m easement within the Christian Camp area, north of the 49A Avenue subdivision, for a drainage ditch from the Old Railway Embankment to Sunset Drive.

Relocate existing drainage ditch within the back of two of lots to the new 20m easement.

Flow Path F, from 49A Avenue to the lake, will be upgraded by lowering the ditch profile and culverts under approaches and roads increased in size to ensure unrestricted flow.

Recommended Time of Work: 2020 - 2023

Phase 2: Construct new drainage ditch within the 20m easement from the Old Railway Embankment to existing drainage ditch location. This work is intended to be necessary to drain the Alberta Beach Golf Course and Future Development areas east of the Christian Camp.

Recommended Time of Work: As required with new development and/or issues with drainage of the golf course.

Phase 3: Within the 49A Avenue and 48th Street subdivision, specific improvements along the Flow Path F will be upgraded by lowering the ditch profile and culverts under approaches and roads increased in size to ensure unrestricted flow. This project is targeted to improve ditch flow in front of lots that are experienced prolonged ponding.

Recommended Time of Work: 2020 - 2023.

Priority #4: **PROJECT #3: 56 Avenue Drainage Improvements**

Re-Grading of existing ditches. Remove existing 400mm culverts and replace with 800mm CSP. Improve other culverts and end treatments within drainage path. Add or resize culverts along Major Drainage Paths.

Recommended Time of Work: 2022 – 2030

Priority #5: **PROJECT #4: Backlot Drainage Swale – 45th Avenue to 48th Avenue**

Construct a new Drainage Swale along the backlots from 45th Avenue to 48th Avenue to ensure flow from south to north. This Drainage Swale will also intercept any flow coming from the future development area to the east. Flow from the Drainage Swale will proceed to a collection area with a sediment bay that will outlet under Sunset Drive to the lake. The existing culverts along this flow path will be upgraded by lowering the ditch profile and culverts under approaches and roads increased in size to ensure unrestricted flow.

Recommended Time of Work: 2022 – 2030

Priority #6: **Poor Culverts**

Replace various culverts that are exhibiting significant issues that will need to be addressed in the next 20 years.

Recommended Time of Work: 2023 – 2030

Priority #7: **Aging Culverts**

Replace various culverts that will reach their design life within the next 20 years and will need rehabilitation or replacement.

Recommended Time of Work: 2030 - 2040

Priority #8: **Other Culverts**

The remainder of the existing culvert infrastructure that will need rehabilitation or replacement due to long-term aging.

Recommended Time of Work: 2040 - 2060

APPENDIX A

Diagram of Project 2: Phase 1,2,3 Boundaries

Summer Village of Sunset Point

W26 54-3-5, NW23 54-3-5 and NE22 54-3-5

Stormwater Management Plan (SWMP)

Legend:

- - - - - Improvement Area Boundary
- Summer Village Boundary
- - - - - Proposed Right of Way
- Proposed Recreational Trail
- - - - - Existing Recreational Trail
- - - - - Proposed Drainage Ditch Phase I
- - - - - Proposed Drainage Ditch Phase II (Extension)
- ▨ Existing Ditch to be Filled
- ⌈ Proposed Culvert
- ⌈ Existing Culvert
- ➔ Proposed Flow Direction
- ➔ Existing Flow Direction



Key Map
N.T.S



Existing Sunset Drive Recreational Trail

Proposed Additional CSP Culvert Crossing Sunset Drive

Proposed Twin CSP Culverts at Trail Crossing

Proposed E-W Drainage Ditch - Phase I (P Ditch-02)

Proposed Recreational Trail

Proposed Right of Way

Tie Drainage Ditch to West Ditch of Railway Embankment

Proposed E-W Drainage Ditch - Phase II

Proposed Ditch Improvements (P Ditch -03)

Remove and Dispose Existing 600mm Culvert (F02)

Fill Existing E-W Drainage Ditch

Tie N-S Ditch to Proposed E-W Drainage Ditch

Regrade Existing N-S Drainage Ditch (P Ditch-01)

Tie Proposed Trail to Existing Recreational Trail on Railway Embankment

Existing 600mm Culvert (F01) @ 3.4% Slope

Optional Phase III (yellow):
Lower Ditch Profile by approx. 0.3 - 1.0m. Involves replacing and lowering all approach and centerline culverts and re-grading ditches.

Scale 1:2,000

- General Notes:
1. 2019 Cadastral Shown
 2. 2019 Aerial Photograph provided by Lac Ste. Anne County

Figure 11
Proposed Central Drainage Way

S:\17- Miscellaneous\Misc-0185 - Sunset Point - SWM Plan\4. Working Drawings\Sunset Point SWMP Figures - APRIL.dwg

APPENDIX B

Drainage Infrastructure Rehabilitation and Improvement Plan

Culvert Rating System by:

1. Priority
 2. Location
 3. Priority Location
-



CULVERT RATING SYSTEM - By Priority
Summer Village of Sunset Point
February 2020



Table with columns: CULVERT NO., CULVERT NAME, MEETS MIN. DIAMETER, CAPACITY, ROADWAY, PIPE BARREL, INLET / OUTLET, SCORE, PROGRAMMING YEAR, ACTION, Improvement/ Replacement Cost.

YEAR 2020 - 2021

PROJECT #1 - Old Railway Embankment & 48A Ave. Drainage Improvements

Table listing culvert details for Project #1, including culvert numbers (e.g., 2741, 2740), names (D01, D02), and associated costs.

YEAR 2020 - 2023

PROJECT #2 - Central Drainage Way incl. 49A Ave. & 48th Street

Table listing culvert details for Project #2, including culvert numbers (e.g., 2713, 2712), names (F01, F02), and associated costs.

YEAR 2022 - 2030

PROJECT #3 - 56th Avenue Drainage Improvements

Table listing culvert details for Project #3, including culvert numbers (e.g., 2611, 2606), names (I05, I04), and associated costs.

YEAR 2022 - 2030

PROJECT #4 - Backlot Drainage Swale - 45 Ave. to 48A Ave.

Table listing culvert details for Project #4, including culvert numbers (e.g., 2202, 2201), names (C01, C02), and associated costs.

YEAR 2020 - 2022 - Blocked Culverts. No Culverts

Table listing culvert details for blocked culverts, including culvert numbers (e.g., 2655, 2660), names (F20, F18), and associated costs.

YEAR 2023 - 2030 - Poor Culverts

Table listing culvert details for poor culverts, including culvert numbers (e.g., 2705, 2701), names (H01, H33), and associated costs.



CULVERT RATING SYSTEM - By Location
Summer Village of Sunset Point
February 2020



Table with columns: CULVERT NO., CULVERT NAME, MEETS MIN. DIAMETER, CAPACITY, ROADWAY, PIPE BARREL, INLET / OUTLET, SCORE, PROGRAMMING YEAR, ACTION, Improvement/ Replacement Cost. Rows include culverts 2729 through 2226.



CULVERT RATING SYSTEM - By Location
Summer Village of Sunset Point
 February 2020



CULVERT NO.	CULVERT NAME	MEETS MIN. DIAMETER (1 Point per Item)		CAPACITY				ROADWAY (1-3 Points per Item)			PIPE BARREL (2 Points per Item)					INLET / OUTLET (1 Point per Item)							SCORE	PROGRAMMING YEAR	ACTION	Improvement/ Replacement Cost			
		Approach Culvert Min. 500mm (Yes = 0 points)	Centreline Road Culvert Min. 600mm (Yes = 0 points)	Major Flow Path (2 Points)	25 Year (0 Points)	10 Year (1 Point)	5 Year (2 Points)	Inadequate Now (3 Points) Emergency: (6 points)	Severe Road Cracking	Pot Holes in Road	Sag in Road	Sag/Bow	Out of Round	Settlement	Infiltration/Cracking/Joint Release	Corrosion 1-Moderate 2-Severe	Blockage	Inlet/Outlet Damage	No Sloped Ends	Sediment Build Up	Erosion above Pipe	Scour below Pipe					Needs Rip Rap	Needs Clearing of Trees/Brush	Needs De-vegetation @ Inverts
54th Avenue & 49th Street																													
2636a	H27a	1					6								1		1									10	2020 - 2022	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 6,100.00
2636	H27	1															1									2	2040 - 2060	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 5,600.00
2637	H28	1														1		1								5	2030 - 2040	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 7,200.00
2633	H29	1													1											4	2040 - 2060	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 5,600.00
2626	H30	1													2		1					1	1	1	7	2030 - 2040	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 6,400.00	
2625	H23	1													2		1					1	1	1	7	2030 - 2040	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 5,600.00	
2624	H22	1															1					1	1	1	5	2030 - 2040	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 8,300.00	
2623	H21	1															1					1	1	1	3	2040 - 2060	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 6,400.00	
2622	H20	1															1					1	1	1	3	2040 - 2060	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 5,100.00	
2621	H24	1														1						1	1	1	4	2040 - 2060	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 5,100.00	
2620	H25	1															1					1	1	1	5	2030 - 2040	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 5,100.00	
2627	I24	1															1					1	1	1	5	2030 - 2040	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 5,100.00	
2628	I20	1															1					1	1	1	3	2040 - 2060	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 2,600.00	
2629	I21	1													1		1					1	1	1	5	2030 - 2040	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 4,100.00	
2630	I22	1															1					1	1	1	3	2040 - 2060	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 5,300.00	
2631	I23	1															1					1	1	1	4	2040 - 2060	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 5,300.00	
2632	H31	1															1					1	1	1	3	2040 - 2060	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 6,000.00	
2619	I11		1														1					1	1	1	7	2030 - 2040	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 9,700.00	
2617	I07		1														1					1	1	1	7	2030 - 2040	Replace with 1-600mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 8,400.00	
2603	I12		1														1					1	1	1	4	2040 - 2060	Replace with 1-600mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 10,600.00	
2602	I06		1														1	1				1	1	1	7	2030 - 2040	Replace with 1-600mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 11,900.00	
56th Avenue & 49th Street																													
2607	I13	1															1	1				1	1	1	5	2030 - 2040	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 6,600.00	
2608	I14																1	1				1	1	1	3	2040 - 2060	Replace with 1-600mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 6,600.00	
2609	I15	1															1	1				1	1	1	4	2040 - 2060	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 6,000.00	
2610	I16	1															1	1				1	1	1	4	2040 - 2060	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 6,000.00	
2613	I17	1															1	1				1	1	1	5	2030 - 2040	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 6,000.00	
2616	I09	1													1		1					1	1	1	4	2040 - 2060	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 6,000.00	
2615	I10	1													1		1					1	1	1	4	2040 - 2060	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 6,000.00	
2614	I19	1															1					1	1	1	4	2040 - 2060	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 6,000.00	
2614b		1					3										1					1	1	1	7	2030 - 2040	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 6,000.00	
2612	I18	1														1	1					1	1	1	5	2030 - 2040	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 6,000.00	
2612b		1					3									1	1					1	1	1	7	2030 - 2040	Replace with 1-500mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 7,100.00	
2618	I07		1														1	2	1	1	1	1	1	1	14	2020 - 2022	Replace with 1-600mm CSP with Sloped Ends, Rip Rap & make longer by 1m per end.	\$ 8,500.00	
2611	I05		1	2		2										1						1	1	1	8	2022 - 2030	Project #3: Install sloped ends and rip rap. Re-Grade upstream ditch.	\$ 5,800.00	
2606	I04		1	2		2										1						1	1	1	8	2022 - 2030	Project #3: Install sloped ends and rip rap.	\$ 2,900.00	
2605	I03		1	2		2										1	1					1	1	1	9	2022 - 2030	Project #3: Replace with 1-800mm CSP with Sloped Ends & Rip Rap.	\$ 73,600.00	
2604	I02		1	2		2										1	1					1	1	1	9	2022 - 2030	Project #3: Remove existing 400mm Dia. Culvert.	\$ 7,200.00	



CULVERT RATING SYSTEM - By Priority Location
Summer Village of Sunset Point
February 2020



Main table with columns: CULVERT NO., CULVERT NAME, MEETS MIN. DIAMETER (1 Point per Item), CAPACITY (25 Year, 10 Year, 5 Year, Inadequate Now), ROADWAY (Severe Road Cracking, Pot Holes, Sag, Sag/Bow, Out of Round, Settlement, Infiltration/Cracking/Joint Release, Corrosion, Blockage), INLET / OUTLET (Inlet/Outlet Damage, No Sloped Ends, Sediment Build Up, Erosion above Pipe, Scour below Pipe, Needs Rip Rap, Needs Clearing of Trees/Brush, Needs De-vegetation @ Inverts), SCORE, PROGRAMMING YEAR, ACTION, Improvement/ Replacement Cost.

Table for 54th Avenue & 49th Street with columns: CULVERT NO., CULVERT NAME, MEETS MIN. DIAMETER, CAPACITY, ROADWAY, INLET / OUTLET, SCORE, PROGRAMMING YEAR, ACTION, Improvement/ Replacement Cost.

Table for 56th Avenue & 49th Street with columns: CULVERT NO., CULVERT NAME, MEETS MIN. DIAMETER, CAPACITY, ROADWAY, INLET / OUTLET, SCORE, PROGRAMMING YEAR, ACTION, Improvement/ Replacement Cost.

APPENDIX C

Design Specifications for Culverts: Detail Drawings and Specifications

Detail Drawings:


1. Approach Treatment for Minor Intersecting Roadway (Intersection of Road and Highway)
2. Corrugated Metal Pipe Culvert Installation
3. Hand Laid Rock Riprap
4. Slope End Installations for Round Section Corrugated Metal Pipe

Detail Drawings:


1. Section 02315 Trenching and Backfilling
 2. Section 02434 Pipe Culverts
 3. Section 02371 Riprap
-

APPROACH TREATMENT FOR MINOR INTERSECTING ROADWAY

INTERSECTION OF ROAD AND HIGHWAY



SECTION A-A INTERSECTING ROAD IN CUT



SECTION A-A INTERSECTING ROAD IN FILL





TABLE 1 - SUGGESTION APPROACH SIDESLOPES *

Primary Highway Posted \geq 100km/h	Fill Height	Desirable Slope on New Approach
Undivided Highway AADT < 1,000	< 4m fill	7:1
	> 4m fill	4:1
Undivided Highway 1,000 < AADT < 3,000	< 4m fill	7:1
	> 4m fill	5:1
Undivided Highway AADT > 3,000	< 4m fill	7:1
	> 4m fill	6:1
Divided Highway AADT < 6,000	< 4m fill	7:1
	> 4m fill	7:1
Divided Highway 6,000 < AADT < 15,000	< 4m fill	8:1
	> 4m fill	7:1
Divided Highway AADT > 15,000	< 4m fill	10:1
	> 4m fill	7:1

* APPROACH TO SLOPE TO BE MEASURED AT A POINT MIDWAY BETWEEN THE HIGHWAY SHOULDER AND BASIC RIGHT-OF-WAY BOUNDARY AS ILLUSTRATED ON FIGURES D-33a AND D-33b

ALGEBRAIC DIFF IN GRADIENT (%)	LENGTH (m)	
	CREST	SAG
1	6	8
2	12	15
3	18	23
4	24	30
5	30	38
6	37	46
7	/	46
8	/	46
9	/	46

NOTE: WHERE THE MINOR INTERSECTING ROADWAY HAS A LARGE NUMBER OF WB-15 VEHICLES TURNING, THE APPROACH TREATMENT SHOWN IN FIGURE D-3.3a SHOULD BE USED.



DETAIL OF DITCH AND CULVERT LOCATION

NOTE: DESIRABLE MINIMUM 1% IS TO PREVENT PONDING AND SUBSEQUENT ICING AT THE INTERSECTION.

DESIRABLE MAXIMUM 2% IS FOR EASE OF OPERATION IN ALL WEATHER CONDITIONS.

APPROACH GRADES BETWEEN 0.5 % AND 3%, ABSOLUTE MAXIMUM 6% ARE CONSIDERED ACCEPTABLE. APPROACH ROAD GRADES UP TO 1% SLOPING DOWN TOWARD THE HIGHWAY MAY BE USED TO MATCH SUPERELEVATION ON THE HIGHWAY, IF DESIRABLE FOR ENGINEERING REASONS.

USE	ROADWAY WIDTH, W * (m)		RADIUS OF INTERSECTION EDGE OF SHOULDER (R)
	SINGLE	JOINT	SINGLE OR JOINT ACCESS
RESIDENTIAL	8	10	10
AGRICULTURAL	10	10.5	15
UTILITY MAINTENANCE	8		15
PUBLIC ROAD ALLOWANCE	8		15

* ENGINEERING DISCRETION SHOULD BE USED IN SELECTING A ROADWAY WIDTH TO SUIT THE NEEDS OF THE ACCESS.



MINIMUM CULVERT REQUIRED

APPROACH: 500mm

CENTERLINE: 600mm



Scale: **N.T.S.**

Date: **JUNE 24, 2020**


Drawn By: **SE Design**

DESIGN SPECIFICATIONS FOR CULVERTS

CORRUGATED METAL PIPE CULVERT INSTALLATION



CLAY SEAL FOR SEEPAGE TO BE PLACED AT BOTH ENDS, FOR A LENGTH OF 3m, AND TO THE TOP OF THE PIPE



MINIMUM CULVERT REQUIRED

APPROACH: 500mm

CENTERLINE: 600mm

Scale: N.T.S.



Date: JUNE 25, 2020

Drawn By: SE Design


DESIGN SPECIFICATIONS FOR CULVERTS

HAND LAID ROCK RIPRAP

SECTION



PLAN VIEW



ELEVATION

NOTES:

- ROCKS AND BOULDERS SHALL BE SELECTED AS NEARLY CUBICAL IN FORM AS PRACTICAL AND SHALL HAVE AT LEAST A MINIMUM DIMENSION OF 200mm. THE STONES SHALL BE PLACED WITH THEIR BEDS AT RIGHT ANGLES TO THE SLOPE, THE LARGER STONES BEING USED IN THE BOTTOM COURSES AND THE SMALLER STONES AT TOP. THEY SHALL BE LAID IN CLOSE CONTACT SO AS TO BREAK JOINTS AND IN SUCH MANNER THAT THE WEIGHT OF THE STONE IS CARRIED BY THE EARTH AND NOT BY THE ADJACENT STONES. THE FINISHED WORK SHALL PRESENT AN EVEN TIGHT, AND REASONABLY PLANE SURFACE, VARYING NOT MORE THAN 75mm FROM THE REQUIRED CONTOUR.
- WHERE NO SPECIAL TREATMENT IS REQUIRED CULVERT INVERT ELEVATIONS ARE TYPICALLY SET ABOUT 0.15 X DIAMETER BELOW THE DRAINAGE COURSE ELEVATION.
- A CLAY SEAL IS TO BE PLACED AT BOTH ENDS OF THE CULVERT FOR A LENGTH OF 3m TO CUT OFF SEEPAGE. THE CLAY SEAL SHALL EXTEND FROM THE BOTTOM OF THE EXCAVATION TO 300mm ABOVE THE CROWN OF THE PIPE AND FOR THE FULL WIDTH OF THE EXCAVATION.
- WHERE APRONS ARE REQUIRED DUE TO HIGH VELOCITY FLOW OR EROSION PRONE SOIL, TYPICALLY THE MINIMUM INLET APRON IS 1.5x DIAMETER LONG WHILE THE MINIMUM OUTLET APRON (WHERE WATER VELOCITY IS HIGHER IS HIGHER) IS TWO DIAMETERS LONG.

ESTIMATED RIPRAP SURFACE AREAS*

PIPE DIAMETER (mm)	AREA OF ONE END EXCLUDING APRON (m ²)	AREA OF ONE END INCLUDING INLET APRON (m ²)	AREA OF ONE END INCLUDING OUTLET APRON (m ²)
500	2	3	4
600	3	5	6
700	4	6	7
800	5	8	9
900	6	10	11
1000	7	12	13
1100	9	14	16
1200	10	16	19
1400	13	22	25

* THE ESTIMATED RIPRAP SURFACE AREAS SHOWN IN THIS TABLE ARE BASED ON A 4:1 SIDESLOPE



MINIMUM CULVERT REQUIRED


APPROACH: 500mm

CENTERLINE: 600mm

Scale: N.T.S.
Date: JUNE 25, 2020
Drawn By: SE Design

DESIGN SPECIFICATIONS FOR CULVERTS

SLOPED END INSTALLATIONS FOR ROUND SECTION CORRUGATED METAL PIPE



SELECTION OF SLOPE RATIO FOR SLOPED END SECTION:

A 4 : 1 SLOPED END SECTION SHALL BE USED IN CONJUNCTION WITH ALL SUBGRADE SIDE SLOPES WITH THE EXCEPTION OF 1200mm DIA. AND LARGER WHERE APPLICABLE.

- DETERMINING INSTALLATION LENGTH
THE LENGTH OF PIPE CULVERT TO BE INSTALLED SHALL BE DETERMINED AS FOLLOWS:
- 1) ESTABLISH THE THEORETICAL LENGTH BASED ON SLOPE STAKE REQUIREMENTS. WHERE NO SPECIAL TREATMENT IS REQUIRED, CULVERT INVERT ELEVATIONS ARE TYPICALLY SET ABOUT 0.15 X DIAMETER BELOW THE DRAINAGE COURSE ELEVATION.
 - 2) ADJUST THE THEORETICAL LENGTH BY APPLYING THE END CORRECTION N AS DETERMINED FROM THE TABLE TO EACH END OF THE CULVERT.
 - 3) INSTALLATION LENGTH SHALL BE THE LENGTH DETERMINED IN "2" ABOVE, ROUNDED OFF TO THE NEAREST METRE.

C.S.P. DIAMETER - D mm	SLOPE RATIO OF CULVERT END X:Y	"N" - m				INVERT LENGTH OF SLOPE END SEC. METRE
		WITH 3:1 SUBGRADE SLOPE RATIO	WITH 4:1 SUBGRADE SLOPE RATIO	WITH 5:1 SUBGRADE SLOPE RATIO	WITH 6:1 SUBGRADE SLOPE RATIO	
400	4:1	0.3	0.5	0.8	1.2	6.0
500	4:1	0.3	0.6	0.9	1.5	6.0
600	4:1	0.3	0.6	1.0	1.6	6.0
700	4:1	0.3	0.8	1.2	2.0	6.0
800	4:1	0.4	0.9	1.4	2.3	6.0
900	4:1	0.5	1.0	1.6	2.5	6.0
1000	4:1	0.5	1.2	1.8	2.8	6.0
1200	3:1	0.5	1.7	2.4	3.7	6.0
	4:1	0.5	1.4	2.2	3.5	6.0
1400	3:1	0.5	1.9	2.8	4.3	6.0
	4:1	0.5	1.6	2.5	3.9	6.0



MINIMUM CULVERT REQUIRED

APPROACH: 500mm

CENTERLINE: 600mm

Scale: N.T.S.

Date: JUNE 25, 2020

Drawn By: SE Design

DESIGN SPECIFICATIONS FOR CULVERTS

1.0 GENERAL

1.1 Definitions

- .1 Common Excavation:
 - .1 Refer to special provision 2000.
- .2 Rock Excavation:
 - .1 The excavation of rock, concrete or masonry exceeding 1.0m³ in volume; and solid ledge rock, concrete or masonry which requires for its removal drilling, blasting, wedging, sledging, barring or breaking with a power operated hand tool shall be classified as rock excavation. Soft or disintegrated rock, concrete or masonry which can be removed with a hand pick, power operated excavator or shovel; and loose, shaken or previously blasted rock will not be classified as rock excavation.
- .3 Class 1 Backfill:
 - .1 Class 1 backfilling shall consist of backfilling the trench with sand or gravel compacted in even layers not exceeding 300mm in depth so that there is no subsequent subsidence in the trench. Backfill shall be compacted to a minimum of 100% Standard Proctor Density. Fillcrete may be used in lieu of Class 1 backfill.
- .4 Class 2 Backfill:
 - .1 Class 2 backfilling shall consist of replacing the excavated material in even layers not exceeding 300 mm in depth, and compacting each layer by mechanical means to 95% Standard Proctor Density in landscaped areas and 98% - 100% Standard Proctor Density within the road carriage way. Specify Standard Proctor Compaction will be indicated on the tender form or directed by the Engineer.
- .5 Topsoil:
 - .1 The top layer of soil containing organic material capable of supporting good vegetative growth and suitable for use in top dressing, landscaping and seeding.

1.2 Protection of Existing Features

- .1 Existing buried utilities and structures:
 - .1 Prior to commencing any excavation work, notify applicable owner or authorities; establish location and state of use of buried utilities and structures. Clearly mark such locations to prevent disturbance during work.
 - .2 Maintain and protect from damage, water, sewer, gas, electric, telephone and other utilities and structures encountered. All damage incurred shall be repaired by the contractor at his expense.
- .2 Existing buildings and surface features:
 - .1 Maintain and protect from damage existing buildings, trees and other plants, lawns, fencing, service poles, wires, rail tracks, paving, survey bench marks and monuments which may be affected by work. All damage incurred shall be repaired by the Contractor at his expense.

1.3 Safety Requirements

- .1 The Contractor shall be required to observe all applicable sections of the Alberta Regulations made under the Occupational Health and Safety Act Part 32 covering worker safety in trenches and excavations.
- .2 Open cut trenches shall be sheeted and braced as required by the Accident Prevention Regulations of the Occupational Health and Safety Division of the Department of Labour and Municipal Ordinances, and as may be necessary to protect life, property and the work.
- .3 Prefabricated cages or shields, provided they conform with all applicable safety requirements, may be used to supplement or replace conventional shoring.

1.4 Samples

- .1 At least 2 weeks prior to commencing work, inform of proposed source of granular materials.
- .2 The Contractor shall provide a sieve analysis of the material for approval.

- .3 Sand and gravel shall be approved before being used.

1.5 Measurement for Payment

- .1 Except as provided elsewhere, trenching, backfilling and compaction will be measured as indicated on the tender form for each depth category and type of backfill used on the following basis:
 - .1 Horizontal measurement shall be measured along the centerline of the trench between manhole centres, fittings to fittings for watermain and from main to the property line for the house service trenches.
 - .2 Measurement between any two manholes or structures for gravity sewers shall be included in one depth category.
 - .3 The depth category between any two manholes or structures for gravity sewers will be calculated by taking the sum of the depths of the pipe at each manhole or structure and dividing by two.
 - .4 The depth of the pipe shall be the depth from the top of the frame to the invert of the pipe in the trench being measured.
- .2 Rock excavation will be measured as indicated on the tender form in its original place. Boulders exceeding 1.0m³ in volume shall be measured complete, as removed from the trench. Ledge rock shall be measured by actual length and actual width of the trench. A greater width than the approved width will not be paid for. Depth shall be measured by the distance from the surface of the rock to the level to which the Engineer orders the rock to be excavated. Any over excavation will not be paid for. Payment for rock excavation shall include hauling and disposing of the material excavated at a location approved, and replacement with suitable material.
- .3 Imported granular material used for stabilizing trench bases and replacement of unsuitable material will be incidental to the trenching price and pipe installation. No extra payment will be made for granular material.

- .4 Filter fabric used for wrapping trench stabilizing gravel will be measured as indicated on the tender form installed. Payment shall be compensation in full for supply and hauling the material to the site, placing, sewing, welding, cutting and all other incidentals necessary to complete the work prescribed.
- .5 The cost of supplying, placing, maintaining and removal of shoring, bracing, cofferdams, underpinning and dewatering will be incidental to the trenching price and pipe installation. No extra payment will be made.

2.0 PRODUCTS

2.1 Stabilizing Base Gravel

- .1 Stabilizing base gravel shall be well graded gravel consisting of hard durable particles free from clay lumps, cementation, organic material, frozen material and other deleterious materials.
- .2 The material shall meet one of the following gradations depending on the native foundation material encountered:

Screened Rock-Washed (Not Crushed)		Crushed Gravel	
Sieve Size (10 ⁻⁶ m)	Percent Passing (by weight)	Sieve Size (10 ⁻⁶ m)	Percent Passing (by weight)
25,000	100	25,000	100
10,000	30-55	20,000	35-60
2,000	5-25	5,000	15-40
400	0-5	400	5-15
		63	0-5

- .3 The liquid limit shall not exceed 25 and the plasticity index shall not exceed 6.

2.2 Filter Fabric

- .1 The synthetic filter fabric shall consist of a durable, permeable, woven, polypropylene fabric composed of continuous synthetic filaments with typical properties as follows:

Tensile Grab Strength — ASTM D4632	890 N
Trapezoid Tear Strength — ASTM D4533	330 N
Mullen Burst Strength — ASTM D3786	2,750 kPa
Puncture—ASTM	400 N

Filter fabric shall be woven Propex 2002, Layfield LP200 or approved equal.

2.3 Bedding and Backfill Material

- .1 Material for Class 1 backfill shall consist of sound, hard, durable, uniformly graded crushed gravel and shall not contain organic or soft materials, materials that break up when alternately frozen and thawed or wetted and dried, or other deleterious materials. When compacted near the optimum moisture content to not less than 100% of the maximum dry density corrected for the stone content as determined by ASTM D698, the material shall have a minimum bearing ratio as defined ASTM D1 883, of fifteen percent (15%).
- .2 Material for Class 2 backfill shall consist of sound, hard, crushed rock or crushed gravel free from organic or soft material that would disintegrate through decay or weathering, well graded throughout confirming to the grading requirement of table below. Class 2 material is to have 100% crush content and be well graded throughout.
- .3 Sand is to be clean and free running conforming to the grading requirements of table below.
- .4 Class 1& 2 material is to have a loss of not more than 35% when subjected to abrasion testing in accordance with Grading B of ASTM C131.
- .5 Imported clay material is to be low to medium plastic clays with liquid limit <50 or mixtures of clay and sand suitable for compaction and is use to be free of silt, rock, concrete rubble and organic materials. Material is to be approved by Engineer before placing in excavation.

TABLE: GRADING REQUIREMENTS FOR IMPORTED BACKFILL

Canadian Metric Sieve Size	Percent of Total Dry Weight Passing Each Sieve		
	Class 1	Class 2	Sand
75,000	90%-100%		
28,000	80%-100%		
20,000		100%	
10,000			100%
5,000	40% - 80%	40% - 70%	90% - 100%
2,500		25% - 60%	
630			25% - 60%
315	10% - 35%	8% - 25%	

2.4 Fillcrete

.1 Non-shrinking fill made up of a mixture of portland cement, sand, water and admixtures conforming to the following:

- | | |
|--|--------------------|
| .1 Minimum 28 day compressive strength | 1.00 to 2.00 MPa |
| .2 Slump | 100 mm \pm 25 mm |
| .3 Portland Cement | Type 10 |
| .4 Air entrainment | 5% \pm 1% |

3.0 EXECUTION

3.1 Site Preparation

.1 Strip organic material, clear and grub, remove weeds and grasses as specified or as required prior to excavation. Avoid intermixing of subsoil fill materials with organic material and from other forms of contamination.

3.2 Trenching

.1 Trench width:

.1 The minimum trench width below the crown of the pipe shall be not less than the nominal diameter of the pipe plus 400mm. The maximum width of the trench below the crown of the pipe including shoring shall not be more than the nominal diameter of the pipe plus 600mm or not more than a total width of 900mm, whichever is larger. Where the maximum trench width

is exceeded, the Contractor shall, at his own expense, provide special bedding or take other precautions as directed by the Engineer.

- .2 The contractor shall confine his activities to the immediate area of the trench. All activities outside the trench boundaries shall be performed so as not to damage other existing features. The Contractor shall generally have the option of using either vertical shored trenches or Vee trenches. Every effort shall be made to restrict the trench widths to minimize the area disturbed.
- .2 All excavated material shall be piled at least 1.0m clear of the trench top to prevent material from falling back into the excavation. The material shall be piled in such a manner that it will not endanger the work, or obstruct other work or rights-of-way. Sufficient clear space must be left on one side of the trench to accommodate the surveyor's stakes.
- .3 The trench shall be excavated so that the pipe can be laid to the alignment, grade and depth required.
- .4 When the walls of an open excavation are cut back, the contractor must ensure that:
 1. If the soil is classified as "hard and compact soil", the walls are sloped to within 1.5 meters of the bottom of the excavation at an angle of not less than 30 degrees measured from the vertical.
 2. If the soil is classified as "likely to crack or crumble soil" the walls are sloped to within 1.5 meters of the bottom of the excavation at an angle of not less than 45 degrees measured from the vertical, and
 3. If the soil is classified as "soft, sandy or loose soil" the walls are sloped from the bottom of the excavation at an angle of not less than 45 degrees measured from the vertical.
- .4 Trench Rock Excavation:
 - .1 Where excavation is made in rock or where excavation is made in a material which cannot provide an even, uniform and smooth surface; or where large stones are encountered in the trench, such material shall be removed to provide a clear distance between any part or projection of such material and the surface of all pipe and fittings of not less than 150mm for 600mm outside diameter pipe or less, and 200mm for pipe having an outside diameter greater than 600mm. The subgrade shall then be made by backfilling with an approved sand compacted in 75mm layers at the Contractors expense. Excavated rock shall not be used for backfill. The finished

subgrade surface shall be shaped by hand tools to provide a uniform and continuous support for the pipe.

- .2 Blasting for excavation will be permitted only with the approval of the Engineer and only when proper precautions are taken for the protection of persons or property. The Contractor's method of procedure in blasting shall conform to provincial statutes and municipal ordinances.
- .5 The subgrade shall provide an uniform and continuous support for the pipe and fittings on solid undisturbed ground. Any over excavation by the Contractor below the required grade shall be backfilled at his expense with an approved compacted sand.

3.3 Classification of Soil Type

- .1 Soil is classified as "hard and Compact" if it closely exhibits most of the following characteristics:
 - .1 it is hard in consistency and can be penetrated only with difficulty by a small, sharp object;
 - .2 it is very dense;
 - .3 it appears to be dry;
 - .4 it has no signs of water seepage;
 - .5 it is extremely difficult to excavate with hand tools;
 - .6 if has not been excavated before.
- .2 Soil is classified as "likely to crack or crumble" if:
 - .1 it has been excavated before but does not exhibit any of the characteristics of "soft, sandy or loose" soil, or
 - .2 it closely exhibits most of the following characteristics:
 - .1 it is stiff in consistency and compacted;
 - .2 it can be penetrated with moderate difficulty with a small, sharp object;
 - .3 it is moderately difficult to excavate with hand tools;
 - .4 it has a low to medium natural moisture content and a damp appearance after it is excavated;
 - .5 it exhibits signs of surface cracking;

- .6 it exhibits signs of localized water seepage
- .3 Soil is classified as “soft, sandy or loose” if it closely exhibits most of the following characteristics:
 - .1 it is firm to very soft in consistency, loose to very loose;
 - .2 it is easy to excavate with hand tools;
 - .3 it is solid in appearance but flows or becomes unstable when disturbed;
 - .4 it runs easily into a well-defined conical pile when dry;
 - .5 it appears to be wet;
 - .6 it is granular below the water table, unless water has been removed from it;
 - .7 it exerts substantial hydraulic pressure when a support system is used.
- .4 if an excavation contains soil or more than one soil type, the contractor must operate as if all of it is the soil type with the least stability.

3.4 Unstable Subgrade

- .1 Where the subgrade of the trench is unstable or will not properly support the pipe, or where it contains materials harmful to the pipe such as ashes, cinders, refuse, vegetable or organic material, the Contractor shall excavate such material to the width, depth and length as directed and dispose of the material. The subgrade shall then be made by backfilling with an approved stabilizing gravel compacted in 75mm layers. The finished subgrade surface shall be shaped by hand tools to provide an uniform and continuous support for the pipe.
- .2 The stabilization gravel may be completely wrapped in the filter fabric as specified. The fabric shall be overlapped a minimum of 500 mm at all joints to provide a full, continuous wrap and shall be smooth and free of tension, stress, folds, wrinkles or creases.
- .3 Where the subgrade cannot be made to properly support the pipe by replacing unsound material with stabilizing gravel, the Contractor shall construct a foundation for the pipe in accordance with a drawing prepared at the time. Payment for this work shall be made in accordance with the provisions for extra work unless specified otherwise.

3.5 Shoring

- .1 When close sheeting is required, it shall be so driven as to prevent adjacent soil from entering the trench either below or through such sheeting. When directed, the sheeting shall be driven to the full depth of the trench or to such additional depths as may be required for the protection of the work.
- .2 Trench bracing may be removed when the backfilling has reached the respective level of such bracing. Sheeting shall be removed as the backfilling proceeds. Backfilling of holes left by sheeting below the trench bottom shall be carefully compacted, and thereafter backfilling and withdrawal of sheeting shall proceed together. No voids shall be left in the backfill by the withdrawal of the sheeting.
- .3 When a cage or shield is used in the trench instead of shoring, special care shall be taken to ensure that there is no lateral or longitudinal movement of the pipe when the cage is moved. The cage shall be raised vertically so that the bottom member is clear of the crown of the pipe before the cage is pulled forward in the trench.

3.6 Trench Drainage and Stormwater Management

- .1 Gutters and natural drainage channels shall not be obstructed. Satisfactory provisions shall be made for alternate drainage where this is impractical.
- .2 The trench shall be so drained that the workmen may work safely and effectively. All water encountered in trenches whether caused by high water table, rain or surface runoff shall be pumped or bailed out, and in no case shall the pipe be used as a drain for such water. It is essential that the discharge of the trench dewatering pumps be conducted away from the site of the work and into natural drainage channels, drains or storm sewers.

- .3 Keep excavations free of water while work is in progress.
- .4 Protect open excavations against flooding and damage due to surface run-off.
- .5 Manage flows in active storm sewer during construction.
- .6 Dispose of water in a manner not detrimental to public and private property, or any portion of work completed or under construction.
- .7 Submit details of proposed surface and stormwater management methods to Engineer for approval prior to start of work.
- .8 All surface run-off, trench drainage and Stormwater Management activities are the responsibility of the contractor. Contractor is to familiarize himself with the geotechnical report (if available) and determine the amount of dewatering effort that will be required to do the work in a safe and efficient manner. No separate payment will be made for dewatering.

3.7 Backfilling

- .1 Bedding and initial backfilling shall be as specified for the particular pipe installed.
- .2 General backfilling:
 - .1 Class 1 backfill as defined in Section 1.1 - Definitions shall be used underneath all existing asphalt road or concrete areas. Class 2 backfill as defined in Section 1.1 - Definitions shall be used in all other areas including future roads, boulevards and open areas
 - .2 No boulders, rock, ice, snow, organic material or debris shall be permitted in the trench. These unsuitable materials shall be hauled away.
 - .3 All surplus excavated material shall also be hauled away, or disposed of as directed. In the event of deficiency of backfill material, suitable material shall be supplied by the Contractor at his expense.
 - .4 All trenches shall be backfilled as the work proceeds and no more than 30 m shall be left open at the end of a days work.

3.8 Backfill Compaction

- .1 The Contractor shall be responsible for adequate compaction of the trenches and for the correction of settlement during the maintenance period of the Contract. Mechanical compaction equipment shall not be used until there is sufficient cover to prevent damage to the pipe.
- .2 The type of compaction equipment shall be chosen with regard to minimizing the vibration effect on nearby buildings and utilities. The Contractor shall inspect the condition of buildings prior to construction. The Contractor is responsible for any damage caused to buildings due to construction.

3.9 Testing Backfill Compaction

- .1 Compaction results shall be based on a minimum of one density test per 100 metres of trench for each 1.0 meter of compacted vertical backfill. Additional tests may be called for by the Engineer as deemed necessary.
- .2 If a density test indicates insufficient compaction at any depth, then two more densities, where are proportionally representative of trench length, shall be taken at that depth. If the average of these tests is below the required density, the trench shall be re-excavated and re-compacted to meet the specified density.
- .3 This testing in no way relieves the Contractor of his maintenance responsibilities with respect to settlements as specified. The Contractor shall repair any settlement and damaged surface improvements due to the settlement which occurs during the maintenance period.
- .4 The cost of all initial testing will be borne by the Contractor. Non-conformity with the specified density or moisture content shall constitute sufficient grounds for rejection of the work.

3.10 Augered/Bored Crossings

- .1 The augering/boring machine shall be aligned and set to the required grade. If the hole deflects from desired course, another hole shall be bored in a location specified. Minimum allowable grades and maximum allowable bends shall be as specified by water mains laid in an open trench.
- .2 The bored hole shall be of sufficient size to allow the carrier pipe or casing pipe, as specified, to pass through unrestricted. After installation of the pipe, the bored hole void shall be backfilled with pneumatically blown free running sand or sealed with 5 MPa pressure grouting.

- .3 Highway crossings shall be cased as shown on the drawings. Casing pipe joints shall be welded. Each joint shall be coated and wrapped with primer and tape.
- .4 Anodes and warning signs shall be installed as specified.

3.11 Fences and Gates

- .1 Maintain gates and fences along and crossing the right-of-way and on access roads.
- .2 Do not open fences crossing the construction right-of-way unless installing the pipe underneath the fence is not feasible.
- .3 Notify landowners and tenants if a fence must be opened. Install temporary gates in accordance with the wishes of the landowners and tenants.
- .4 Return fences to original condition as soon as fence openings or alterations are no longer required for construction.

END OF SECTION

1.0 GENERAL

1.1 Related Work

- .1 Trenching, Backfilling and Compaction: Section 02315.

1.2 Measurement for Payment

- .1 Excavation and backfill for culverts will not be measured separately.
- .2 Supply and installation of pipe culvert including trenching, backfilling, compaction, geotech fabric, riprap and culvert markers will be measured as indicated on the tender form in place for each size, type and class of pipe.

2.0 PRODUCTS

2.1 Corrugated Steel Pipe

- .1 Corrugated steel pipe: to CSPI-501-78 metric (interim). Corrugated steel pipe. Note: CSPI specifications may be obtained from Corrugated Steel Pipe Institute, Suite 207, Crestview Plaza, 1640 Crestview Avenue, Mississauga, Ontario, L5G 3P9 or affiliated member.

3.0 EXECUTION

3.1 Excavation and Preparation of Base

- .1 Excavation for the culvert base shall be to a depth of not less than 0.3m below the invert grade, and shall be of sufficient width to permit assembly of the pipe and the operation of compaction equipment on either side of the pipe. All soft, yielding, or unsuitable material at this level shall be removed to a depth as directed by the Engineer, and replaced with gravel or other suitable material to provide a firm foundation of uniform density throughout the entire length of the pipe.
- .2 On completion of excavation for the culvert base and the removal and replacement of any soft, yielding or unsuitable material the Contractor shall compact the exposed surface to uniform density. The Contractor shall then construct the culvert bed to the established elevation using gravel material or other material acceptable to the Consultant. The culvert bed shall be compacted in accordance with Section 02315. The width of the culvert bed shall be 3 times the culvert diameter.
- .3 Contractor to ensure sufficient clay "cap" compacted around the culvert to prevent erosion on the sides of the culvert.

- .4 When the culvert installation is in rock, excavation for the culvert base shall be carried out to a depth of not less than 0.2m below the invert grade. The width of the culvert bed shall be a minimum of 1.5 times the diameter of the pipe.
- .5 Where gravel bedding or backfill is used, impervious, compacted clay cut-offs shall be constructed at both ends of the culvert.
- .6 Do trenching and backfill work to Section 02315.
- .7 Do not backfill until pipe grade and alignment checked and accepted by the Engineer.

4.0 INSTALLATION

4.1 General

- .1 The culvert shall be installed on the prepared base, true to the designed lines and grades unless otherwise established by the Engineer. Separate sections shall be securely joined in accordance with the manufacturer's instructions. Coupler bands shall be used for metal and polyethylene pipe unless otherwise specified, rubber gasket type joints shall be prepared and made between sections or reinforced concrete pipe. At all coupling and joint areas and at areas of concrete pipe that have external bells, depressions shall be constructed in the culvert bed so that the pipe is uniformly supported along its entire length.
- .2 Contractor to install culvert markers as per detail on page 5. Approved supplier for culvert markers: Canada Culvert Steelcor CSP or similar acceptable product to be approved by Engineer.
- .3 The Contractor shall use due care when installing pipe to avoid damaging the pipe. Damaged pipe shall be removed and replaced by the Contractor at his expense.

4.2 Installation of Corrugated Metal Pipe and Pipe Arches

- .1 When required, elbows shall be installed to accommodate sharp changes in gradient or direction of the pipe.
- .2 Pipe shall be carefully handled to prevent damage to the protective coating. Any damage to coatings shall be repaired by the Contractor at his own expense.
- .3 Ensure bottom of pipe is in contact with shaped bed or compacted fill throughout its length. Ensure proper clay "cap" surrounding the pipe to prevent erosion.

- .4 Lay pipe with outside circumferential laps facing upstream.
- .5 Do not allow water to flow through pipes during construction except as permitted by Engineer.

4.3 Joints: Corrugated Steel Culverts

- .1 Corrugated steel pipe:
 - .1 Match corrugations or identifications of coupler with pipe sections before tightening.
 - .2 Tap couplers firmly as they are being tightened, to take up slack and ensure a snug fit.
 - .3 Insert and tighten bolts.

4.4 Installation of Reinforced Concrete Pipe

- .1 Reinforced Concrete Pipe shall be placed beginning at the downstream or lower end of the culvert. The pipes shall be placed with the bell or grooved ends facing upstream.
- .2 Pipe shall be joined using either a wedge and block or mechanical pipe pullers to bring the pipe to the homed position. Joints shall not be deflected beyond the manufacturer's recommended maximum.
- .3 End sections shall be anchored to adjacent sections by tie bars, where provided. Lifting holes and holes for engaging bars shall be filled with mortar and finished flush with the pipe surface.

4.5 Installation of Polyethylene Pipe

- .1 The culvert bed shall be shaped to the curvature of the pipe to a depth of 75mm using a template.
- .2 Blocking shall not be used to bring the pipe to grade. The pipe shall be placed on the prepared base to the lines and grades established by the Engineer, with the separate sections securely joined with the applicable welds and gasket joints.
- .3 Temporary hold downs shall be used to maintain the position of the pipe during installation.
- .4 Section of pipe with a minimum length of 6m shall be used on each end of each culvert.

4.6 Extension of Existing Culvert

- .1 Extensions to existing culverts will be considered as new installations. Where an existing culvert is to be extended, the removal, salvage and reinstallation of the existing sloped end sections may be required as directed by the Engineer.
- .2 Where the existing pipe was manufactured to imperial dimensions and the new pipe is manufactured to metric dimensions and a mismatch occurs at the joint, the Contractor shall caulk the joint with oakum or fillcrete to obtain a water resistant joint.

5.0 BACKFILLING

5.1 General

- .1 Backfill under the haunches and immediately adjacent to the pipe extending from the culvert base up to an elevation of 30 percent of the vertical height of the pipe shall be comprised of select gravel or soil material, as directed by the Engineer. Backfill immediately adjacent to the pipe above this level shall be comprised of select soil material. All backfill material shall be free from frozen lumps and organic material. Backfill with 300mm of the pipe wall shall be free from stones of diameter larger than 80mm.
- .2 All backfill material shall be placed in layers not exceeding 0.15m in depth. Each layer shall be thoroughly compacted at optimum moisture content by means of pneumatic or other mechanical tamping equipment. Backfill and compaction layers shall be brought up simultaneously and evenly on both sides of the pipe filling all corrugations and ensuring firm contact with the entire bottom surface of the pipe. This compaction procedure shall be continued until the backfill reaches a minimum elevation of 0.3m above the top of the pipe, or greater if necessary to carry the weight of construction equipment without damage to the pipe.
- .3 The Contractor is to ensure a proper seal around the culvert ends at both ends of the culvert. This can be achieved with suitable material such as Clay to ensure the water does not erodes the sides and underside of the culverts eventually rendering the culvert ineffective possibly causing a washout of the road. The "clay" cap should be a minimum of 1.0m in length.
- .4 If during the warranty period, it is determine by the Engineer that the culvert is rendered ineffective due to improper seal at both ends of the culvert, the Contractor will be responsible at his own cost to repair all the damages which may include but not limited to installing a new culvert, bringing new borrow material for proper culvert installation,

geotech fabric, riprap, and for the road restoration: subgrade preparation, gravel, asphalt, line painting as detailed in the contract) that may have been caused by the poor workmanship. Contractor responsible to carry-out the repairs to the approval of the Engineer. Contractor to refer to Special Provision 2000 with regards to Emergency Repairs.


- .5 Backfilling of the remainder of the culvert excavation, beyond the immediate region of the pipe, shall be carried out in accordance with section 2315. Compacting equipment shall be operated parallel to the longitudinal axis of the culvert, until sufficient acceptable fill has been placed to proceed with construction of the embankment in the normal manner.

5.2 Backfilling Polyethylene Pipe

- .1 The minimum height of fill above the top of the pipe is 0.6m rather than 0.3m. Immediately after backfill is completed, the Contractor shall saw cut the sloped ends at a ratio of 4:1.

5.3 Culvert Markers

- .1 Contractor to submit shop drawings to the engineer for approval the culvert marker selected. Culvert marker is to be bright color (orange or red) similar to orange tubing of the SteelCor CSP Culvert Markers. Culvert Marker to be affix with spring loaded tubing so it does not brake if accidently hit (refer to detail in this specification section).



END OF SECTION

1.0 GENERAL

1.1 Measurement for Payment

- .1 Riprap will be measured as indicated on the tender form to the top of finished surface for the quantity of rock riprap acceptably supplied and placed within the dimensions indicated on the drawings or as required by the Engineer.
- .2 Where indicated on the tender form, payment for riprap on culverts will be included as part of the culvert installation.
- .3 Materials placed outside the specific areas will not be measured. Payment shall be compensation in full for transportation, excavation, bedding, backfilling and all other incidentals necessary to complete the work prescribed. Unless otherwise indicated no direct measurement will be made for the supply and placement of the synthetic filter fabric which shall be considered incidental to work.
- .4 Measurement for geotextile fabric will be included as part of the culvert installation.

2.0 PRODUCTS

2.1 Rock Riprap

- .1 Materials for rock riprap shall be sound and durable field stone, or rough unhewn quarry stone as nearly rectangular as practicable, conforming to the following graduation and weight range:
 - .1 Maintain and protect from damage, water, sewer, gas, electric, telephone and other utilities and structures encountered. All damage incurred shall be repaired by the contractor at his expense.

Sieve Size [mm]	Weight [kg]	Percent Passing [by weight]
300	21	100% smaller
200	11	20% larger
150	5	50% larger
100	2	80% larger

- .2 The rock riprap shall be graded between the weights specified.

2.2 Filter Fabric (Geotextile)

- .1 The synthetic filter fabric shall consist of a durable, permeable, woven, polypropylene fabric composed of continuous synthetic filaments with typical properties as follows:

Tensile Grab Strength — ASTM D4632	890 N
Trapezoid Tear Strength — ASTM D4533	330 N
Mullen Burst Strength — ASTM D3786	2,750 kPa
Puncture—ASTM	400 N

Filter fabric shall be woven Propex 2002, Layfield LP200 or approved equal.

3.0 EXECUTION

3.1 Placing

- .1 The hand laid rock riprap erosion protection shall be placed in the areas indicated on the Drawings or as designated by the Engineer
- .2 Placement of Filter Fabric
- .1 The surface to receive the riprap shall be smooth, well dressed and prepared with the synthetic filter fabric.
- .2 The areas to be covered by the synthetic filter fabric shall be trimmed and dressed to the lines and grades shown on the Drawings or as required by the Engineer.
- .3 The synthetic filter fabric shall be placed on the dressed surfaces to cover the areas that are the rock riprap erosion protection. The fabric shall be overlapped a minimum of 500 mm at all joints to provide a full, continuous mat and shall be laid smooth and free of tension, stress, folds, wrinkles, or creases. Securing pins and washers shall be inserted through both strips of overlapped fabric at no greater than 1 m intervals along a line through the midpoint of the overlap, and at intervals necessary to prevent slippage of the fabric on the downslopes. Each securing pin shall be pushed through the fabric until the washer bears against the fabric firmly and secures it to the foundation. The indicated filter fabric may also be overlapped as specified and welded at the seams.

- .4 The fabric placed on the inlet and outlet aprons shall be laid perpendicular to the centre line of the culvert and shall be laid so that the upslope strip of fabric will overlap the downslope strip
- .3 Riprap Placement:
 - .1 Nominal size 150 mm riprap, as defined in Section 2.0- Products shall be used.
 - .2 The riprap stones shall be placed on the surface to be covered as shown by the plans or as directed by the Engineer, on slopes not exceeding 1 1/2H:1V starting with the larger stones on the bottom row. Each stone shall be placed with the broad flat surface resting on a horizontal earth bed prepared for it such that the weight of the stone is carried by the earth and not by the underlying stones. Stones shall be laid in successive rows, or layers, proceeding upward with the joints staggering those of the adjacent rows as so to secure a 'shingled' effect, evenly stepped. Voids between stones shall be filled with spalls rammed into place.
 - .3 Care shall be taken not to puncture the synthetic filter fabric when placing the riprap. Any damaged filter fabric shall be repaired or replaced at the contractor's expense as directed by the Engineer.

END OF SECTION

APPENDIX D

Culvert Inspection Reports – Sorted By Location

EXISTING INFRASTRUCTURE REVIEW
SUMMER VILLAGE OF SUNSET POINT
FEBRUARY 2020



SE DESIGN AND CONSULTING INC.

ENGINEERS • CONSULTANTS • SURVEYORS

48A Avenue Culvert Inspection Reports

Date:

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	Lot 55 & 54 Approach	S. Side	2685 - D07

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
	Box	

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	600	mm
Slope	1.6	%
Length	12.35	m

Overall Rating
9

Roadway Over Pipe	Response
Pavement cracks or Patches	Yes
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.3

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Needs Apron



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	<5 Year



Comments

No Backslope along ditch; risk of flow going into Lot.
Flow will be increased here due to changes upstream.



Inspected By: _____ D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2685 - D07

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	820.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	14	\$ 350.00	\$ 4,900.00
4		Supply & Install 600mm C.S.P. Culvert Sloped Ends	m	3	\$ 350.00	\$ 1,050.00
5		Supply & Install Rip Rap	unit	4	\$ 150.00	\$ 600.00
6		Light Grading	lump sum	1	\$ 1,500.00	\$ 1,500.00
7		Backslope Building/Grading	lump sum	1	\$ 2,000.00	\$ 2,000.00
Sub-Total						\$ 11,020.00
10% Contingencies:						\$ 1,102.00
8% Admin & Engineering:						\$ 881.60
TOTAL:						\$ 13,100.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date: November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	Lot 53 Approach	N. Side	2686 - F17

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	2.8	%		
		Thickness	1.6mm		Length	8.16	m	


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.5 - 1.0

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	Yes
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	Negligible

Comments
Paved Approach. Barrell pushed in on one end.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2686 - F17

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	395.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
Sub-Total						\$ 4,345.00
10% Contingencies:						\$ 434.50
8% Admin & Engineering:						\$ 347.60
TOTAL:						\$ 5,200.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	Lot 56 Approach	S. Side	2687 - D06

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
	Box	

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	600	mm
Slope	0.5	%
Length	10.09	m

Overall Rating
9

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.3

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	Needs More



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	<5 Year

Comments
 Very good condition except for bent East end.
 East end bent on top. Straight faced ends.
 Some rip rap. 0.3 cover

 Flow will be increased here due to changes upstream.



Inspected By: D. Paulichuk, P. Eng.
 Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2687 - D06

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	750.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	12	\$ 350.00	\$ 4,200.00
4		Supply & Install 600mm C.S.P. Culvert Sloped Ends	m	3	\$ 350.00	\$ 1,050.00
5		Supply & Install Rip Rap	unit	4	\$ 150.00	\$ 600.00
6		Light Grading	lump sum	1	\$ 1,500.00	\$ 1,500.00
Sub-Total						\$ 8,250.00
10% Contingencies:						\$ 825.00
8% Admin & Engineering:						\$ 660.00
TOTAL:						\$ 9,800.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

October 17, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	Lot 20 & 19 Approach	N. Side	2688 - D17

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	300	mm
Slope	2.2	%
Length	10.01	m

Overall Rating
4

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.5 - 1.0

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	Needs More



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 yrs

Comments
 Lot 19 vacant. Dual approach. Ends bent.
 Lots of grass. No rip rap.
 0.5 - 1.0 cover



Inspected By: D. Paulichuk, P. Eng.
 Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2688 - D17

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	455.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	12	\$ 300.00	\$ 3,600.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
Sub-Total						\$ 5,005.00
10% Contingencies:						\$ 500.50
8% Admin & Engineering:						\$ 400.40
TOTAL:						\$ 6,000.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	Lot 57 Approach	S. Side	2689 - D05

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	9
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	600	mm	
Box		Steel	✓	Slope	1.2	%		
			Thickness	1.6mm	Length	10.26	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.3

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	Needs More

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	<5 Year

Comments
Very good condition. 0.3m cover. Rip rap on top. Poor rip rap apron. Grown over with grass Straight face end. Flow will be increased here due to changes upstream.

Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2689 - D05

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	750.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	12	\$ 350.00	\$ 4,200.00
4		Supply & Install 600mm C.S.P. Culvert Sloped Ends	m	3	\$ 350.00	\$ 1,050.00
5		Supply & Install Rip Rap	unit	4	\$ 150.00	\$ 600.00
6		Light Grading	lump sum	1	\$ 1,500.00	\$ 1,500.00
Sub-Total						\$ 8,250.00
10% Contingencies:						\$ 825.00
8% Admin & Engineering:						\$ 660.00
TOTAL:						\$ 9,800.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	Large Area Approach	S. Side	2690 - D04

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	9
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	600	mm	
	Box		Steel	✓	Slope	1.7	%	
		Thickness	1.6mm	Length	12.29	m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.0

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	Needs More

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	<5 Year

Comments
 Very good condition. Approach to empty bush.
 Rip rap on top of culvert but need on apron
 Straight ends.

 Flow will be increased here due to changes upstream.



Inspected By: _____ D. Paulichuk, P. Eng.
 Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2690 - D04

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	820.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	14	\$ 350.00	\$ 4,900.00
4		Supply & Install 600mm C.S.P. Culvert Sloped Ends	m	3	\$ 350.00	\$ 1,050.00
5		Supply & Install Rip Rap	unit	4	\$ 150.00	\$ 600.00
6		Light Grading	lump sum	1	\$ 1,000.00	\$ 1,500.00
Sub-Total						\$ 9,020.00
10% Contingencies:						\$ 902.00
8% Admin & Engineering:						\$ 721.60
TOTAL:						\$ 10,700.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date: October 17, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	Lot 21 & 22 Approach	N. Side	2691 - D16

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	1.6	%		
		Thickness	1.6mm		Length	15.69	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.0

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	Needs More

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 yrs

Comments
 Good shape. Straight face end - very slightly bent. Pavement failure on approaches, Centerline crac over culvert. Low cover <0.2m on East end. No rip rap, lots of grass Standing water in culvert, no rust. Cover on west end 0.7m .



Inspected By: D. Paulichuk, P. Eng.
 Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2691 - D16

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	623.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	17.6	\$ 300.00	\$ 5,280.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
Sub-Total						\$ 6,853.00
10% Contingencies:						\$ 685.30
8% Admin & Engineering:						\$ 548.24
TOTAL:						\$ 8,100.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	E. End of 48A Ave.	Centreline	2693 - D08

Pipe Details:	Shape (Select One)	Material (Select One)	Pipe Size		Overall Rating																															
	<table border="1"> <tr><td>Arch</td><td></td></tr> <tr><td>Circular</td><td>✓</td></tr> <tr><td>Elliptical</td><td></td></tr> <tr><td>Box</td><td></td></tr> </table>	Arch		Circular	✓	Elliptical		Box		<table border="1"> <tr><td>Aluminum</td><td></td></tr> <tr><td>Concrete</td><td></td></tr> <tr><td>Plastic</td><td></td></tr> <tr><td>Steel</td><td>✓</td></tr> <tr><td>Thickness</td><td>1.6mm</td></tr> </table>	Aluminum		Concrete		Plastic		Steel	✓	Thickness	1.6mm	<table border="1"> <tr><td>Span</td><td></td><td>mm</td></tr> <tr><td>Rise</td><td></td><td>mm</td></tr> <tr><td>Diameter</td><td>600</td><td>mm</td></tr> <tr><td>Slope</td><td>0.9</td><td>%</td></tr> <tr><td>Length</td><td>22.22</td><td>m</td></tr> </table>	Span		mm	Rise		mm	Diameter	600	mm	Slope	0.9	%	Length	22.22	m
Arch																																				
Circular	✓																																			
Elliptical																																				
Box																																				
Aluminum																																				
Concrete																																				
Plastic																																				
Steel	✓																																			
Thickness	1.6mm																																			
Span		mm																																		
Rise		mm																																		
Diameter	600	mm																																		
Slope	0.9	%																																		
Length	22.22	m																																		

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	<1.0

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	<5Yrs.

Comments
Improvements to the flow coming from east of the old railway embankment are anticipated to take most of flow away from this culvert. However, this culvert is expected to drain the west area of the embankment area, taking away runoff from the backyards of the lots. Improvements for this culvert are more in the line of grading upstream to ensure the flow reaches this culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2693 - D08

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	685.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert Sloped Ends	m	4	\$ 350.00	\$ 1,400.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Re-Grading Upstream Ditch	lump sum	1	\$ 5,000.00	\$ 5,000.00
Sub-Total						\$ 7,535.00
10% Contingencies:						\$ 753.50
8% Admin & Engineering:						\$ 602.80
TOTAL:						\$ 8,900.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	Lot 23 & 24 Approach	N. Side	2730 - D15

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
	Box	

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	300	mm
Slope	0.7	%
Length	11.98	m

Overall Rating
6


Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.0

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	Needs More

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5 Yrs.

Comments
Ok shape, Small culvert and grass grown in. Lots of grass grown around ends. Dual approach for lot 24 & 23, being used. No sloped ends, no noticeable rust, no rip rap.



Inspected By: _____ D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2730 - D15


Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	515.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	14	\$ 300.00	\$ 4,200.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
Sub-Total						\$ 5,665.00
10% Contingencies:						\$ 566.50
8% Admin & Engineering:						\$ 453.20
TOTAL:						\$ 6,700.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	Lot 24 Approach	N. Side	2731 - D14

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	1.8	%		
			Thickness	1.6mm	Length	14.78	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.0



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	Needs More

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 yrs

Comments
Fairly good shape. 1m cover. Outlet (rip rap around pipe but needs more on apron. Dual approach - Lot 25 not being used. No rip rap on inlet side, no slope ends, no noticeable rust or dip. Water in pipe.

Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2731 - D14

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	605.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	17	\$ 300.00	\$ 5,100.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
Sub-Total						\$ 6,655.00
10% Contingencies:						\$ 665.50
8% Admin & Engineering:						\$ 532.40
TOTAL:						\$ 7,900.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	Lot 25 & 26 Approach	N. Side	2732 - D13

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	2.6	%		
		Thickness	1.6mm		Length	16.2	m	

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.2 - 1.5

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 yrs

Comments
48 A Ave, North Side, 2nd approach to resident. 1.2 - 1.5 m cover. No rip rap. Clean grass away from culvert ends. Part of culvert is for dual approach but not used to Lot 25 to the East. No one in Lot 25. Water in pipe.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2732 - D13

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	635.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	18	\$ 300.00	\$ 5,400.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
Sub-Total						\$ 6,985.00
10% Contingencies:						\$ 698.50
8% Admin & Engineering:						\$ 558.80
TOTAL:						\$ 8,300.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	Lot 26 Approach	N. Side	2733 - D12

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	2.5	%		
		Thickness	1.6mm		Length	6.47	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.3 - 0.5

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 yrs

Comments
North side of 48A Ave. 0.3 to 0.5m cover. No rip rap. Clean grass away from culvert ends. Water in pipe.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2733 - D12

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	365.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
Sub-Total						\$ 4,015.00
10% Contingencies:						\$ 401.50
8% Admin & Engineering:						\$ 321.20
TOTAL:						\$ 4,800.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	Lot 27 Approach	N. Side	2734 - D11

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	1.4	%		
		Thickness	1.6mm		Length	8.87	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.6 - 0.9

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 yrs

Comments
N. Side 48 A Avenue - Approach to Resident. Lots of grass at ends of culvert that could be cleaned out. No rip rap. Cover 0.6 to 0.9. No dip. Water in pipe.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2734 - D11

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	425.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	11	\$ 300.00	\$ 3,300.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
Sub-Total						\$ 4,675.00
10% Contingencies:						\$ 467.50
8% Admin & Engineering:						\$ 374.00
TOTAL:						\$ 5,600.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	N. Side, E. of Sunset Dr.	Multi-Use Trail	2735 - D10

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Score
	Arch		Aluminum		Span		mm	7
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
	Box		Steel	✓	Slope	1.2	%	
		Thickness	1.6mm	Length	2.32	m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	Yes
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5 yrs

Comments
Straight ends, no cover, no rust, no dip, no rip rap, could clean outside ends of grass buildup, scape marks on top with galvanization, could be painted.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2735 - D10

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	245.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	5	\$ 300.00	\$ 1,500.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
Sub-Total						\$ 2,695.00
10% Contingencies:						\$ 269.50
8% Admin & Engineering:						\$ 215.60
TOTAL:						\$ 3,200.00

PROJECT NAME:	2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	E. Side of Sunset Dr.	Centreline	2736 - D09

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	8
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	600	mm	
	Box		Steel	✓	Slope	0.6	%	
		Thickness	1.6mm	Length	13.96	m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.0

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	Yes
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	Yes
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	<5 yrs

Comments
48A Avenue Culvert to Sunset Drive - East side of Sunset Drive. Damaged North end and South end. No rip rap. Ends need cleaning (very bad), Steep S/S N. end and S. End. Make longer 1m per end. Culvert clogged and can not see thru. Dipping in the center and towards the lake. Area is not draining and this culvert needs to be lowered as a overall area lowering of the ditches and culverts to the lake.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2736 - D09

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	725.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 800mm C.S.P. Culvert	m	16	\$ 425.00	\$ 6,800.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	30	\$ 82.50	\$ 2,475.00
					Sub-Total	\$ 10,450.00
					10% Contingencies:	\$ 1,045.00
					8% Admin & Engineering:	\$ 836.00
					TOTAL:	\$ 12,400.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	S. Side, E. of Sunset Dr.	Multi-Use Trail	2737 - D03

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
	Box	

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	400	mm
Slope	0.36	%
Length	2.76	m

Overall Score
10

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	Yes
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	<5 yrs

Comments
48A Avenue, South side, East of Sunset Drive. Quad trail over culvert. Straight ends. Ends damaged. No rust, no dip. Grass cover culvert ends. No rip rap. Flow will be increased here due to changes upstream.



Inspected By: _____ D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2737 - D03

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	495.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	6	\$ 350.00	\$ 2,100.00
4		Supply & Install 600mm C.S.P. Culvert	m	6	\$ 350.00	\$ 2,100.00
5		Supply & Install Rip Rap	unit	4	\$ 150.00	\$ 600.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
Sub-Total						\$ 5,945.00
10% Contingencies:						\$ 594.50
8% Admin & Engineering:						\$ 475.60
TOTAL:						\$ 7,100.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date: September 27, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48A Avenue	S. Side, E. of Sunset Dr.	Multi-Use Trail	2737 - D03

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Score
	Arch		Aluminum		Span		mm	10
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	0.36	%		
		Thickness	1.6mm		Length	2.76	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	Yes
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	<5 yrs

Comments
 48A Avenue, South side, East of Sunset Drive. Quad trail over culvert. Straight ends. Ends damaged. No rust, no dip. Grass cover culvert ends. No rip rap. Flow will be increased here due to changes upstream.



Inspected By: D. Paulichuk, P. Eng.
 Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2737 - D03

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	495.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	6	\$ 350.00	\$ 2,100.00
4		Supply & Install 600mm C.S.P. Culvert	m	6	\$ 350.00	\$ 2,100.00
5		Supply & Install Rip Rap	unit	4	\$ 150.00	\$ 600.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
Sub-Total						\$ 5,945.00
10% Contingencies:						\$ 594.50
8% Admin & Engineering:						\$ 475.60
TOTAL:						\$ 7,100.00

EXISTING INFRASTRUCTURE REVIEW
SUMMER VILLAGE OF SUNSET POINT
FEBRUARY 2020

SE DESIGN AND CONSULTING INC.

ENGINEERS • CONSULTANTS • SURVEYORS

Old Railway Embankment Culvert Inspection Reports

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	
	S.V. of Sunset Point	Old Railway Embankment	N. of 48A Avenue	Centreline	2692 - RE02

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	13
Circular	✓	Concrete		Rise		mm		
Elliptical		Plastic		Diameter	500	mm		
Box		Steel	✓	Slope	1.8	%		
		Thickness	1.6mm	Length	15.5	m		


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	>1.0

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	Inadequate

Comments
Flow is very high and flowing to the west and should be draining to the south along old railway embankment. Improvements are recommended to take flow coming from east of the old railway embankment which will take all of the flow away from this culvert. This culvert should be removed as it will become redundant. Improvement work will take flow from the Golf Course and re-direct to south ditch of 48A Avenue via an underground storm sewer.

Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2692 - RE02

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 2,175.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove and Salvage Existing 500mm CSP	m	16	\$ 100.00	\$ 1,600.00
4		Re-Grading Upstream Ditch, West Side of Embank. for 200m	lump sum	1	\$ 20,000.00	\$ 20,000.00
5		Install Underground Storm Sewer with Manholes - See Estimate Below	m	16	\$ 100.00	\$ 97,264.84
Sub-Total						\$ 121,189.84
10% Contingencies:						\$ 12,118.98
8% Admin & Engineering:						\$ 9,695.19
TOTAL:						\$ 143,100.00

North Side Only

						<u>Factored</u>
General Requirements	lump	1	\$	10,000.00	\$	4,062.50
Clearing and Grubbing	ha	0.25	\$	6,500.00	\$	660.16
Topsoil Stripping and Stockpiling	m2	3800	\$	2.25	\$	3,473.44
Remove & Salvage Existing Culvert	unit	1	\$	1,500.00	\$	1,500.00
Trenching & Backfilling for Storm Sewer Pipe	m	330	\$	140.00	\$	18,768.75
Supply and Install 450mm Ultrarib Storm Pipe	m	320	\$	145.00	\$	18,850.00
Supply and Install 600mm Ultrarib Storm Pipe	m	10	\$	245.00	\$	2,450.00
Supply and Install 450mm End Treatment	unit	2	\$	4,000.00	\$	8,000.00
Supply and Install 600mm End Treatment	unit	1	\$	4,500.00	\$	4,500.00
Supply and Install 900mm Catchbasin	unit	1	\$	6,500.00	\$	6,500.00
Supply and Install 1800mm Catchbasin Mahole w/Control	unit	1	\$	22,000.00	\$	22,000.00
Replace Topsoil and Groom	m2	4000	\$	4.00	\$	6,500.00
\$						97,264.84

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	
	S.V. of Sunset Point	Old Railway Embankment	N. of 48A Avenue	Centreline	2692 - RE02b

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span	mm	13
Circular		Concrete		Rise	mm		
Elliptical		Plastic		Diameter	mm		
Box		Steel		Slope	%		
		Thickness		Length	m		

Roadway Over Pipe	Response
Pavement Cracks or Patches	
Sag in Roadway	
Recent signs of high water	
Amount of Cover (m)	

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	
Embankment Erosion	
Sideslopes too Steep	
Drift - wood, debris around pipe	
Vegetation - trees, brush etc.	
Silt	
Rip Rap	

Pipe Barrel	Rating
Blockage	
Submerged in Water	
Inlet Damage	
Outlet damage	
Corrosion / Abrasion	
Out of Round	
Settlement	
Sag / Bow	
Infiltration	
Piping	
Cracking	

Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	Inadequate

Comments
Could not find this culvert. Records from the old railway embankment construction indicate that a culvert did exist in this area. Flow is high in this area coming from the golf course. Flow should mostly go south along old railway embankment. Improvements are recommended to take this flow mostly to the south to 48A Avenue on both sides of the railway embankment. Some flow is to go to the north where a new drainage course is to be constructed north of the lots. This culvert will be redundant after improvements.



Did Not Find this Culvert

Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2692b - RE02b

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	2,000.00
4		Re-Grading Upstream Ditch, West Side of Embank. for 250m	lump sum	1	\$ 20,000.00	\$ 20,000.00
Sub-Total						\$ 22,000.00
10% Contingencies:						\$ 2,200.00
8% Admin & Engineering:						\$ 1,760.00
TOTAL:						\$ 26,000.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	
	S.V. of Sunset Point	Old Railway Embankment	S. of 48A Avenue	Centreline	2692c - RE02c

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	10
	Circular		Concrete		Rise		mm	
	Elliptical		Plastic		Diameter		mm	
Box		Steel		Slope		%		
			Thickness		Length		m	

Roadway Over Pipe	Response
Pavement Cracks or Patches	
Sag in Roadway	
Recent signs of high water	
Amount of Cover (m)	

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	
Embankment Erosion	
Sideslopes too Steep	
Drift - wood, debris around pipe	
Vegetation - trees, brush etc.	
Silt	
Rip Rap	

Pipe Barrel	Rating
Blockage	
Submerged in Water	
Inlet Damage	
Outlet damage	
Corrosion / Abrasion	
Out of Round	
Settlement	
Sag / Bow	
Infiltration	
Piping	
Cracking	



Did Not Inspect this Culvert

Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	Inadequate

Comments
 Flow is high and is not properly set in elevation as water flow goes from the west and goes east into golf course. All flow should go to the west through vacant land. Improvements are recommended to take flow coming from east of the old railway embankment which will take all of the flow away from this culvert. This culvert should be removed as it will become redundant. Improvement work will take flow from the Golf Course and re-direct to south ditch of 48A Avenue via an underground storm sewer.

Inspected By: D. Paulichuk, P. Eng.
 Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2692c - RE02c

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 175.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove and Salvage Existing 500mm CSP	m	16	\$ 100.00	\$ 1,600.00
4		Install Underground Storm Sewer with Manholes - See Estimate Below	m	16	\$ 100.00	\$ 94,960.16
Sub-Total						\$ 96,885.16
10% Contingencies:						\$ 9,688.52
8% Admin & Engineering:						\$ 7,750.81
TOTAL:						\$ 114,400.00

South Side Only

General Requirements	lump	1	\$ 10,000.00	\$ 5,937.50
Clearing and Grubbing	ha	0.25	\$ 6,500.00	\$ 964.84
Topsoil Stripping and Stockpiling	m2	3800	\$ 2.25	\$ 5,076.56
Remove & Salvage Existing Culvert	unit	1	\$ 1,500.00	\$ 1,500.00
Trenching & Backfilling for Storm Sewer Pipe	m	330	\$ 140.00	\$ 27,431.25
Supply and Install 450mm Ultrarib Storm Pipe	m	320	\$ 145.00	\$ 27,550.00
Supply and Install 600mm Ultrarib Storm Pipe	m	0	\$ 245.00	\$ -
Supply and Install 450mm End Treatment	unit	1	\$ 4,000.00	\$ 4,000.00
Supply and Install 600mm End Treatment	unit	0	\$ 4,500.00	\$ -
Supply and Install 900mm Catchbasin	unit	2	\$ 6,500.00	\$ 13,000.00
Supply and Install 1800mm Catchbasin Mahole w/Control	unit	0	\$ 22,000.00	\$ -
Replace Topsoil and Groom	m2	4000	\$ 4.00	\$ 9,500.00
				\$ 94,960.16

North Side Only

General Requirements	lump	1	\$ 10,000.00	<u>Factored</u> 4,062.50
Clearing and Grubbing	ha	0.25	\$ 6,500.00	\$ 660.16
Topsoil Stripping and Stockpiling	m2	3800	\$ 2.25	\$ 3,473.44
Remove & Salvage Existing Culvert	unit	1	\$ 1,500.00	\$ 1,500.00
Trenching & Backfilling for Storm Sewer Pipe	m	330	\$ 140.00	\$ 18,768.75
Supply and Install 450mm Ultrarib Storm Pipe	m	320	\$ 145.00	\$ 18,850.00
Supply and Install 600mm Ultrarib Storm Pipe	m	10	\$ 245.00	\$ 2,450.00
Supply and Install 450mm End Treatment	unit	2	\$ 4,000.00	\$ 8,000.00
Supply and Install 600mm End Treatment	unit	1	\$ 4,500.00	\$ 4,500.00
Supply and Install 900mm Catchbasin	unit	1	\$ 6,500.00	\$ 6,500.00
Supply and Install 1800mm Catchbasin Mahole w/Control	unit	1	\$ 22,000.00	\$ 22,000.00
Replace Topsoil and Groom	m2	4000	\$ 4.00	\$ 6,500.00
				\$ 97,264.84

EXISTING INFRASTRUCTURE REVIEW
SUMMER VILLAGE OF SUNSET POINT
FEBRUARY 2020

SE DESIGN AND CONSULTING INC.

ENGINEERS • CONSULTANTS • SURVEYORS

48th Street Culvert Inspection Reports

Culvert Inspection Report

Date: Friday, November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 41 & 42 Approach	E. Side	2654 - F26

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
	Box	

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size	
Span	mm
Rise	mm
Diameter	400 mm
Slope	1.8 %
Length	8.72 m

Overall Rating
5

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.3

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	Yes
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert in fair condition. Approach is not paved. End treatments poor & damaged; could use sloped ends. Some silt.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2654 - F26

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	395.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	35	\$ 40.00	\$ 1,400.00
Sub-Total						\$ 5,745.00
10% Contingencies:						\$ 574.50
8% Admin & Engineering:						\$ 459.60
TOTAL:						\$ 6,800.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 11 & 12 Approach	W. Side	2655 - F20

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
	Box	

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	300	mm
Slope	1.6	%
Length	6.08	m

Overall Rating
5

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.3



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	Yes
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	Negligible

Comments
Culvert in fair condition. Approach is not paved. North end is damaged; can't find south end & may be buried; could use sloped ends. Trees on south end make drainage difficult.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2655 - F20

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	395.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	35	\$ 40.00	\$ 1,400.00
Sub-Total						\$ 5,745.00
10% Contingencies:						\$ 574.50
8% Admin & Engineering:						\$ 459.60
TOTAL:						\$ 6,800.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 42 & 43 Approach	E. Side	2656 - F25

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	300	mm
Slope	3.9	%
Length	14.01	m

Overall Rating
6

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	Yes
Recent signs of high water	No
Amount of Cover (m)	0.3



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	Yes
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
 Culvert in fair condition. Dips on Approach that hold water. Approach is not paved. End treatments poor & damaged; could use sloped ends. Can't see through culvert. 1/3 full of silt.

Inspected By: D. Paulichuk, P. Eng.
 Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2656 - F25

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	545.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	15	\$ 300.00	\$ 4,500.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	35	\$ 40.00	\$ 1,400.00
Sub-Total						\$ 7,395.00
10% Contingencies:						\$ 739.50
8% Admin & Engineering:						\$ 591.60
TOTAL:						\$ 8,800.00

Culvert Inspection Report

Date: Friday, November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 44 & 45 Approach	E. Side	2670 - F24

Pipe Details:

Shape (Select One)	
Arch	
Circular	✓
Elliptical	
Box	

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	500	mm
Slope	3.3	%
Length	7.6	m

Overall Rating
5

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	Yes
Recent signs of high water	No
Amount of Cover (m)	0.3

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	Yes
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year



Comments

Culvert in fair to good condition. Dip on Approach that holds water. Approach is not paved. End treatments poor; could use sloped ends. Tree/bush at S. End needs to be cleared.

Inspected By: D. Paulichuk, P. Eng.
 Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2670 - F24

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	395.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	35	\$ 40.00	\$ 1,400.00
Sub-Total						\$ 5,745.00
10% Contingencies:						\$ 574.50
8% Admin & Engineering:						\$ 459.60
TOTAL:						\$ 6,800.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lots 44/45 to Lot 39a	Centerline	2671 - F08

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	600	mm
Slope	0.8	%
Length	13.56	m

Overall Rating
4

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.75



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	100 Year

Comments
Culvert interior is in good condition. Culverts need sloped ends. On Major Drainage path from old railway embankment. Recommend once this culvert has aged and reached its design life, replace with one 800mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2671 - F08

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	815.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m	0	\$ 100.00	\$ -
4		Supply & Install 800mm C.S.P. Culvert	m	15	\$ 480.00	\$ 7,200.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	24	\$ 82.50	\$ 1,980.00
Sub-Total						\$ 10,945.00
10% Contingencies:						\$ 1,094.50
8% Admin & Engineering:						\$ 875.60
TOTAL:						\$ 13,000.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 47 & 48 Approach	E. Side	2672 - F27

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	400	mm
Slope	2.0	%
Length	11.55	m

Overall Rating
5

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.3

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	Yes
Inlet Damage	No
Outlet damage	Yes
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert in fair to good condition. Mostly submerged which is concerning as it provides little capacity for more flow. Low flow area. Expensive driveway replacement. End treatments poor; could use sloped ends.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2672 - F27

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	585.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	14	\$ 350.00	\$ 4,900.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	30	\$ 82.50	\$ 2,475.00
Sub-Total						\$ 8,910.00
10% Contingencies:						\$ 891.00
8% Admin & Engineering:						\$ 712.80
TOTAL:						\$ 10,600.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date: Friday, November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 39a Approach	W. Side	2673 - F10

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	2
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	600	mm	
Box		Steel	✓	Slope	1.9	%		
		Thickness	1.6mm		Length	10.19	m	

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.5

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	100

Comments
Culvert interior is in very good condition. Some water and little siltation. With future drainage re-direction upstream at the old railway embankment, this flow path will change from a Major Flow path to a Minor Flow path. Recommend once this culvert has aged and reached its design life, remove and will be replaced by 2674/F09.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2673 - F10

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	-
2		Channel Excavation	m3	0	\$ 150.00	\$ -
3		Supply & Install 800mm C.S.P. Culvert	m	0	\$ 480.00	\$ -
4		Supply & Install Rip Rap	unit	0	\$ 150.00	\$ -
5		Light Grading	lump sum	0	\$ 500.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
					Sub-Total	\$ -
					10% Contingencies:	\$ -
					8% Admin & Engineering:	\$ -
					TOTAL:	\$ -

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2673 - F10

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
LOWERING GRADE, PROJECT #2 Phase 3						
1		Mobilization - 10%	lump sum		\$	142.50
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove and Dispose of 600mm C.S.P. Culvert	m	10.2	\$ 125.00	\$ 1,275.00
3		Supply & Install 600mm C.S.P. Culvert	m	0	\$ 350.00	-
4		Supply & Install Rip Rap	unit	0	\$ 150.00	-
5		Light Grading	lump sum	0	\$ 500.00	-
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	-
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	-
Sub-Total						\$ 1,567.50
10% Contingencies:						\$ 156.75
8% Admin & Engineering:						\$ 125.40
TOTAL:						\$ 1,900.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 39a Approach	W. Side	2674 - F09

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
	Box	

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	600	mm
Slope	0.3	%
Length	12.09	m

Overall Rating
2

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.5



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	100

Comments
Culvert interior is in very good condition. Some water and little siltation. Flat grade within a major flow path. Culverts stick out too much and need sloped ends. With future drainage re-direction upstream at the old railway embankment, this flow path will change from a Major Flow path to a Minor Flow path. Recommend once this culvert has aged and reached its design life, replace with one 800mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2674 - F09

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	719.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 800mm C.S.P. Culvert	m	13	\$ 480.00	\$ 6,240.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	20	\$ 82.50	\$ 1,650.00
Sub-Total						\$ 9,559.00
10% Contingencies:						\$ 955.90
8% Admin & Engineering:						\$ 764.72
TOTAL:						\$ 11,300.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2674 - F09


Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
LOWERING GRADE, PROJECT #2 Phase 3						
1		Mobilization - 10%	lump sum		\$	425.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove, Salvage & Reinstall 600mm C.S.P. Culvert	m	12	\$ 150.00	\$ 1,800.00
3		Supply & Install 800mm C.S.P. Culvert	m	4	\$ 375.00	\$ 1,500.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	20	\$ 82.50	\$ 1,650.00
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
Sub-Total						\$ 6,325.00
10% Contingencies:						\$ 632.50
8% Admin & Engineering:						\$ 506.00
TOTAL:						\$ 7,500.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 46 to Lot 13	Centerline	2675 - F11

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	2
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	600	mm	
Box		Steel	✓	Slope	1.2	%		
		Thickness	1.6mm		Length	13.99	m	

Roadway Over Pipe	Response
Pavement Cracks or Patches	Yes
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.75



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	100 Year

Comments
Culvert interior is in very good condition. Culverts stick out too much and need sloped ends. With future drainage re-direction upstream at the old railway embankment, this flow path will change from a Major Flow path to a Minor Flow path. Recommend once this culvert has aged and reached its design life, replace with one 800mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2675 - F11

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	-
2		Channel Excavation	m3	0	\$ 150.00	\$ -
3		Remove & Salvage 500mm C.S.P. Culvert	m	0	\$ 100.00	\$ -
4		Supply & Install 800mm C.S.P. Culvert	m	0	\$ 480.00	\$ -
5		Supply & Install Rip Rap	unit	0	\$ 150.00	\$ -
6		Light Grading	lump sum	0	\$ 500.00	\$ -
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
					Sub-Total	\$ -
					10% Contingencies:	\$ -
					8% Admin & Engineering:	\$ -
					TOTAL:	\$ -

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2675 - F11

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
LOWERING GRADE, PROJECT #2 Phase 3						
1		Mobilization - 10%	lump sum		\$	410.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove, Salvage & Reinstall 600mm C.S.P. Culvert	m	14	\$ 150.00	\$ 2,100.00
3		Supply & Install 600mm C.S.P. Culvert	m	3	\$ 350.00	\$ 1,050.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	20	\$ 82.50	\$ 1,650.00
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
Sub-Total						\$ 6,160.00
10% Contingencies:						\$ 616.00
8% Admin & Engineering:						\$ 492.80
TOTAL:						\$ 7,300.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 13 & 14 Approach	W. Side	2676 - F28

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	3
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	0.6	%		
		Thickness	1.6mm		Length	16.05	m	

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.3

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	Inadequate

Comments
Culvert in fair to good condition. Little siltation. Flat grade but not within a major flow path. Capacity is noted as inadequate from capacity analysis however this is mainly due to pipe slope and not high flow. Recommend not to rate capacity as inadequate but as 25 year capacity.

Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2676 - F28

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	635.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	18	\$ 300.00	\$ 5,400.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	32	\$ 82.50	\$ 2,640.00
Sub-Total						\$ 9,625.00
10% Contingencies:						\$ 962.50
8% Admin & Engineering:						\$ 770.00
TOTAL:						\$ 11,400.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 47 & 48 Approach	E. Side	2677 - F13

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	600	mm
Slope	0.6	%
Length	12.3	m

Overall Rating
3

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.3




Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5 Year

Comments
Culvert in very good condition. Little siltation. Flat grade but not within a major flow path. Capacity is noted as 5 Year from capacity analysis however this is mainly due to pipe slope and not high flow. Recommend not to rate capacity as inadequate but as 25 year capacity. End treatments poor; could use sloped ends.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2677 - F13

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	515.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	14	\$ 300.00	\$ 4,200.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	28	\$ 82.50	\$ 2,310.00
Sub-Total						\$ 7,975.00
10% Contingencies:						\$ 797.50
8% Admin & Engineering:						\$ 638.00
TOTAL:						\$ 9,500.00

Culvert Inspection Report


Date: Friday, November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 15 & 16 Approach	W. Side	2678 - F29

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	3
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
	Box		Steel	✓	Slope	0.8	%	
		Thickness	1.6mm	Length	19.9	m		

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.3



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	Inadequate

Comments
Culvert in fair to good condition. Little siltation. Flat grade but not within a major flow path. Capacity is noted as inadequate from capacity analysis however this is mainly due to pipe slope and not high flow. Recommend not to rate capacity as inadequate but as 25 year capacity.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2678 - F29

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	695.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	20	\$ 300.00	\$ 6,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	40	\$ 82.50	\$ 3,300.00
Sub-Total						\$ 10,945.00
10% Contingencies:						\$ 1,094.50
8% Admin & Engineering:						\$ 875.60
TOTAL:						\$ 13,000.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 49 & 50 Approach	E. Side	2679 - F14a

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	500	mm
Slope	0.9	%
Length	12.3	m

Overall Rating
7

Roadway Over Pipe	Response
Pavement Cracks or Patches	Yes
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.5



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	Yes
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	Yes
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert interior is in very good condition. Lots of issues with end treatments. Flat grade but not within a major flow path. Water ponds in ditch to the south; home owner uses sump pump to pump from ditch to culvert. Ditch re-grading and culvert elevation reset required.



Inspected By: _____ D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2679 - F14a

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	625.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m	12.5	\$ 100.00	\$ 1,250.00
4		Supply & Install 600mm C.S.P. Culvert - reset elevation	m	13	\$ 350.00	\$ 4,550.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	0	\$ 500.00	\$ -
7		Re-Grade Ditch	lump sum	1	\$ 2,000.00	\$ 2,000.00
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	24	\$ 82.50	\$ 1,980.00
Sub-Total						\$ 10,855.00
10% Contingencies:						\$ 1,085.50
8% Admin & Engineering:						\$ 868.40
TOTAL:						\$ 12,900.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2679 - F14a

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
LOWERING GRADE, PROJECT #2 Phase 3						
1		Mobilization - 10%	lump sum		\$	342.50
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove, Salvage & Reinstall 500mm C.S.P. Culvert	m	12.5	\$ 150.00	\$ 1,875.00
3		Supply & Install 500mm C.S.P. Culvert	m	2	\$ 300.00	\$ 600.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	20	\$ 82.50	\$ 1,650.00
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
Sub-Total						\$ 5,417.50
10% Contingencies:						\$ 541.75
8% Admin & Engineering:						\$ 433.40
TOTAL:						\$ 6,400.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 49 & 50 Approach	E. Side	2679 - F14b

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	7
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	500	mm	
Box		Steel	✓	Slope	0.0	%		
		Thickness	1.6mm		Length	11.6	m	

Roadway Over Pipe	Response
Pavement Cracks or Patches	Yes
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.5

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	Yes
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	Yes
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert interior is in fair to good condition. Lots of issues with end treatments. Flat grade but not within a major flow path. Water ponds in ditch to the south; home owner uses sump pump to pump from ditch to culvert. Ditch re-grading and culvert elevation reset required. This culvert not needed.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2679 - F14b

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	125.00
2		Channel Excavation	m3	0	\$ 150.00	\$ -
3		Remove & Salvage 500mm C.S.P. Culvert	m	12.5	\$ 100.00	\$ 1,250.00
4		Supply & Install 600mm C.S.P. Culvert - reset elevation	m	0	\$ 350.00	\$ -
5		Supply & Install Rip Rap	unit	0	\$ 150.00	\$ -
6		Light Grading	lump sum	0	\$ 500.00	\$ -
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
Sub-Total						\$ 1,375.00
10% Contingencies:						\$ 137.50
8% Admin & Engineering:						\$ 110.00
TOTAL:						\$ 1,700.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2679 - F14b

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
LOWERING GRADE, PROJECT #2 Phase 3						
1		Mobilization - 10%	lump sum		\$	160.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove and Dispose of 600mm C.S.P. Culvert	m	11.6	\$ 125.00	\$ 1,450.00
3		Supply & Install 600mm C.S.P. Culvert	m	0	\$ 350.00	\$ -
4		Supply & Install Rip Rap	unit	0	\$ 150.00	\$ -
5		Light Grading	lump sum	0	\$ 500.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
Sub-Total						\$ 1,760.00
10% Contingencies:						\$ 176.00
8% Admin & Engineering:						\$ 140.80
TOTAL:						\$ 2,100.00

PROJECT NAME:

2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 17 Approach	W. Side	2680 - F30

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	0.4	%		
		Thickness	1.6mm		Length	4.9	m	

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.3

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	Yes
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	Inadequate

Comments
Culvert in fair to good condition. Some internal staining. Some siltation. Flat grade but not within a major flow path. Capacity is noted as inadequate from capacity analysis however this is mainly due to pipe slope and not high flow. Recommend not to rate capacity as inadequate but as 25 year capacity.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2680 - F30

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	335.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	8	\$ 300.00	\$ 2,400.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
Sub-Total						\$ 3,685.00
10% Contingencies:						\$ 368.50
8% Admin & Engineering:						\$ 294.80
TOTAL:						\$ 4,400.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 18 Approach	W. Side	2681 - F31

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	300	mm
Slope	0.4	%
Length	11.2	m

Overall Rating
4

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.3

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Needs More



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert in fair to good condition. Some internal staining with some rust. Flat grade but not within a major flow path. Capacity is noted as inadequate from capacity analysis however this is mainly due to pipe slope and not high flow. Recommend not to rate capacity as inadequate but as 25 year capacity.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2681 - F31

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	455.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	12	\$ 300.00	\$ 3,600.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	24	\$ 82.50	\$ 1,980.00
Sub-Total						\$ 6,985.00
10% Contingencies:						\$ 698.50
8% Admin & Engineering:						\$ 558.80
TOTAL:						\$ 8,300.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 52 Approach	E. Side	2682 - F15

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
	Box	

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	300	mm
Slope	2.7	%
Length	11.5	m

Overall Rating
3

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.3

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Needs More



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert in good condition. Ponding in the ditch due to poor ditch grading. Lots of rock, but very little rock for apron.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2682 - F15

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	455.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	12	\$ 300.00	\$ 3,600.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	24	\$ 82.50	\$ 1,980.00
Sub-Total						\$ 6,985.00
10% Contingencies:						\$ 698.50
8% Admin & Engineering:						\$ 558.80
TOTAL:						\$ 8,300.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 53 Approach	E. Side	2683 - F16

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	3
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
	Box		Steel	✓	Slope	0.7	%	
Thickness	1.6mm			Length	9.4	m		

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.3

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Needs More



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert in very good condition. Ponding in the ditch due to poor ditch grading. Culvert is sticking out on one end which is hazardous.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2683 - F16

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	425.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	11	\$ 300.00	\$ 3,300.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	22	\$ 82.50	\$ 1,815.00
Sub-Total						\$ 6,490.00
10% Contingencies:						\$ 649.00
8% Admin & Engineering:						\$ 519.20
TOTAL:						\$ 7,700.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	48 Street	Lot 46 to Lot 13	Centerline	2694 - F12

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
	Box	

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	600	mm
Slope	1.2	%
Length	13.99	m

Overall Rating
2

Roadway Over Pipe	Response
Pavement Cracks or Patches	Yes
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.75



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	100 Year

Comments
Culvert interior is in very good condition. Culverts stick out too much and need sloped ends. With future drainage re-direction upstream at the old railway embankment, this flow path will change from a Major Flow path to a Minor Flow path. Recommend once this culvert has aged and reached its design life, replace with one 800mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2694 - F12

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	815.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m	0	\$ 100.00	\$ -
4		Supply & Install 800mm C.S.P. Culvert	m	15	\$ 480.00	\$ 7,200.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	24	\$ 82.50	\$ 1,980.00
Sub-Total						\$ 10,945.00
10% Contingencies:						\$ 1,094.50
8% Admin & Engineering:						\$ 875.60
TOTAL:						\$ 13,000.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2694 - F12

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
LOWERING GRADE, PROJECT #2 Phase 3						
1		Mobilization - 10%	lump sum		\$	190.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove and Dispose of 600mm C.S.P. Culvert	m	14	\$ 125.00	\$ 1,750.00
3		Supply & Install 600mm C.S.P. Culvert	m	0	\$ 350.00	-
4		Supply & Install Rip Rap	unit	0	\$ 150.00	-
5		Light Grading	lump sum	0	\$ 500.00	-
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	-
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	-
Sub-Total						\$ 2,090.00
10% Contingencies:						\$ 209.00
8% Admin & Engineering:						\$ 167.20
TOTAL:						\$ 2,500.00

EXISTING INFRASTRUCTURE REVIEW
SUMMER VILLAGE OF SUNSET POINT
FEBRUARY 2020

SE DESIGN AND CONSULTING INC.

ENGINEERS • CONSULTANTS • SURVEYORS

49A Avenue Culvert Inspection Reports

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49A Avenue	Lot 10 & 12 Approach	N. Side	2657 - F19

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	0.9	%		
		Thickness	1.6mm	Length	12.14	m		

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.50

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	None


Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	Negligible

Comments

Culvert in fair condition (S. Culvert). Approach is not paved. Bushes near east end will make drainage difficult and should be cleared. When replaced, it is important to re-set slope on culvert to ensure flow is from east to west. Second culvert (smoothwall) is private and drains Lot 12 into ditch. This private culvert makes approach culvert redundant. Lot grading should be reviewed before any replacement work is done. Ideally, this location should be reduced to 1 culvert.

Inspected By: D. Paulichuk, P. Eng.
Name



**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2657 - F19

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	515.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	14	\$ 300.00	\$ 4,200.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	35	\$ 40.00	\$ 1,400.00
					Sub-Total	\$ 7,065.00
					10% Contingencies:	\$ 706.50
					8% Admin & Engineering:	\$ 565.20
					TOTAL:	\$ 8,400.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date: Friday, November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49A Avenue	Lot 39A Approach	S. Side	2658 - F07a

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	8
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	0.2	%		
		Thickness	1.6mm		Length	12.24	m	


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.75

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	Yes
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	Yes
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	Inadequate

Comments
Culvert in fair condition (S. Culvert). Approach is not paved. Some issues with deformation. Bushes near ends will make drainage difficult and should be cleared. When replaced, it is important to re-set slope on culvert to ensure flow is from east to west.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2658 - F07a

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	585.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	14	\$ 350.00	\$ 4,900.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	35	\$ 40.00	\$ 1,400.00
Sub-Total						\$ 7,835.00
10% Contingencies:						\$ 783.50
8% Admin & Engineering:						\$ 626.80
TOTAL:						\$ 9,300.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2658 - F07a

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
LOWERING GRADE, PROJECT #2 Phase 3						
1		Mobilization - 10%	lump sum		\$	845.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Dipose 400mm C.S.P. Culvert	m	12.5	\$ 120.00	\$ 1,500.00
3		Supply & Install 800mm C.S.P. Culvert	m	16	\$ 375.00	\$ 6,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	35	\$ 82.50	\$ 2,887.50
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
Sub-Total						\$ 12,182.50
10% Contingencies:						\$ 1,218.25
8% Admin & Engineering:						\$ 974.60
TOTAL:						\$ 14,400.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49A Avenue	Lot 39A Approach	S. Side	2659 - F07b

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	600	mm
Slope	0.3	%
Length	12.23	m

Overall Rating
10

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.75



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	Yes
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	Inadequate

Comments
Culvert in poor condition (N. Culvert) and has reduced capacity. Approach is not paved. Bushes near ends will make drainage difficult and should be cleared. When replaced, it is important to re-set slope on culvert to ensure flow is from east to west.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2659 - F07b

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	585.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	14	\$ 350.00	\$ 4,900.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	35	\$ 40.00	\$ 1,400.00
Sub-Total						\$ 7,835.00
10% Contingencies:						\$ 783.50
8% Admin & Engineering:						\$ 626.80
TOTAL:						\$ 9,300.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2659 - F07b

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
LOWERING GRADE, PROJECT #2 Phase 3						
1		Mobilization - 10%	lump sum		\$	171.25
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove and Dispose of 400mm C.S.P. Culvert	m	12.5	\$ 125.00	\$ 1,562.50
3		Supply & Install 600mm C.S.P. Culvert	m	0	\$ 350.00	-
4		Supply & Install Rip Rap	unit	0	\$ 150.00	-
5		Light Grading	lump sum	0	\$ 500.00	-
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	15	\$ 82.50	\$ 1,237.50
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	-
Sub-Total						\$ 3,121.25
10% Contingencies:						\$ 312.13
8% Admin & Engineering:						\$ 249.70
TOTAL:						\$ 3,700.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2660 - F18

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	455.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	12	\$ 300.00	\$ 3,600.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	35	\$ 40.00	\$ 1,400.00
Sub-Total						\$ 6,405.00
10% Contingencies:						\$ 640.50
8% Admin & Engineering:						\$ 512.40
TOTAL:						\$ 7,600.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49A Avenue	Lot 37 & 38 Approach	S. Side	2661 - F05


Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
	Box	

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	400	mm
Slope	0.8	%
Length	12.21	m

Overall Rating
4

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.70



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Sideslope

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	Yes
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	Inadequate

Comments
Culvert in fair condition. Rusting should be monitored. Approach is paved with a headwall on the east side.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2661 - F05

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	585.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	14	\$ 350.00	\$ 4,900.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	25	\$ 82.50	\$ 2,062.50
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
Sub-Total						\$ 8,497.50
10% Contingencies:						\$ 849.75
8% Admin & Engineering:						\$ 679.80
TOTAL:						\$ 10,100.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2661 - F05

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
LOWERING GRADE, PROJECT #2 Phase 3						
1		Mobilization - 10%	lump sum		\$	171.25
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove and Dispose of 400mm C.S.P. Culvert	m	12.5	\$ 125.00	\$ 1,562.50
3		Supply & Install 600mm C.S.P. Culvert	m	0	\$ 350.00	-
4		Supply & Install Rip Rap	unit	0	\$ 150.00	-
5		Light Grading	lump sum	0	\$ 500.00	-
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	15	\$ 82.50	\$ 1,237.50
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	-
Sub-Total						\$ 3,121.25
10% Contingencies:						\$ 312.13
8% Admin & Engineering:						\$ 249.70
TOTAL:						\$ 3,700.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49A Avenue	Lot 37 & 38 Approach	S. Side	2662 - F06


Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
	Box	

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	600	mm
Slope	1.6	%
Length	11.94	m

Overall Rating
4

Roadway Over Pipe	Response
Pavement Cracks or Patches	Yes
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.70



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Sideslope

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	Inadequate

Comments
Culvert in very good condition. Approach is paved with a headwall on the east side.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2662 - F06

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	585.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	14	\$ 350.00	\$ 4,900.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	25	\$ 82.50	\$ 2,062.50
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
Sub-Total						\$ 8,497.50
10% Contingencies:						\$ 849.75
8% Admin & Engineering:						\$ 679.80
TOTAL:						\$ 10,100.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2662 - F06

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
LOWERING GRADE, PROJECT #2 Phase 3						
1		Mobilization - 10%	lump sum		\$	764.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Dipose 600mm C.S.P. Culvert	m	12	\$ 120.00	\$ 1,440.00
3		Supply & Install 800mm C.S.P. Culvert	m	14	\$ 375.00	\$ 5,250.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	35	\$ 82.50	\$ 2,887.50
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
Sub-Total						\$ 11,291.50
10% Contingencies:						\$ 1,129.15
8% Admin & Engineering:						\$ 903.32
TOTAL:						\$ 13,400.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49A Avenue	Lot 37 to Lot 7/8	Centerline (East)	2663 - F03


Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
	Box	

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	600	mm
Slope	0.5	%
Length	18.23	m

Overall Rating
4

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.70



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Sideslope

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	10 Year



Comments
Culvert in very good condition. Steep sideslope on south side; grassed headwall north side. When replacing, ensure to provide some slope from south the north.

Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2663 - F03

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	795.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	20	\$ 350.00	\$ 7,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	30	\$ 82.50	\$ 2,475.00
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
Sub-Total						\$ 11,220.00
10% Contingencies:						\$ 1,122.00
8% Admin & Engineering:						\$ 897.60
TOTAL:						\$ 13,300.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2663 - F03

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
LOWERING GRADE, PROJECT #2 Phase 3						
1		Mobilization - 10%	lump sum		\$	1,067.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Dipose 600mm C.S.P. Culvert	m	18.5	\$ 120.00	\$ 2,220.00
3		Supply & Install 800mm C.S.P. Culvert	m	20	\$ 375.00	\$ 7,500.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	40	\$ 82.50	\$ 3,300.00
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
Sub-Total						\$ 15,037.00
10% Contingencies:						\$ 1,503.70
8% Admin & Engineering:						\$ 1,202.96
TOTAL:						\$ 17,800.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49A Avenue	Lot 37 to Lot 7/8	Centerline (West)	2664 - F04


Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
	Box	

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	600	mm
Slope	0.4	%
Length	18.23	m

Overall Rating
4

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.70



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Sideslope

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	10 Year



Comments
Culvert in very good condition. Steep sideslope on south side; grassed headwall north side. When replacing, ensure to provide some slope from south the north.

Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2664 - F04

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	795.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	20	\$ 350.00	\$ 7,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	30	\$ 82.50	\$ 2,475.00
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
Sub-Total						\$ 11,220.00
10% Contingencies:						\$ 1,122.00
8% Admin & Engineering:						\$ 897.60
TOTAL:						\$ 13,300.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2664 - F04

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
LOWERING GRADE, PROJECT #2 Phase 3						
1		Mobilization - 10%	lump sum		\$	246.25
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove and Dispose of 600mm C.S.P. Culvert	m	18.5	\$ 125.00	\$ 2,312.50
3		Supply & Install 600mm C.S.P. Culvert	m	0	\$ 350.00	-
4		Supply & Install Rip Rap	unit	0	\$ 150.00	-
5		Light Grading	lump sum	0	\$ 500.00	-
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	-
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	-
Sub-Total						\$ 2,708.75
10% Contingencies:						\$ 270.88
8% Admin & Engineering:						\$ 216.70
TOTAL:						\$ 3,200.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2665 - F21

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	455.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	12	\$ 300.00	\$ 3,600.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	50	\$ 82.50	\$ 4,125.00
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 9,130.00
10% Contingencies:						\$ 913.00
8% Admin & Engineering:						\$ 730.40
TOTAL:						\$ 10,800.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2666 - F22

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	395.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	35	\$ 40.00	\$ 1,400.00
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 5,745.00
10% Contingencies:						\$ 574.50
8% Admin & Engineering:						\$ 459.60
TOTAL:						\$ 6,800.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2667 - F23

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	455.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	12	\$ 300.00	\$ 3,600.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	30	\$ 82.50	\$ 2,475.00
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 7,480.00
10% Contingencies:						\$ 748.00
8% Admin & Engineering:						\$ 598.40
TOTAL:						\$ 8,900.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2668 - E07

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	485.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	13	\$ 300.00	\$ 3,900.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	30	\$ 82.50	\$ 2,475.00
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 7,810.00
10% Contingencies:						\$ 781.00
8% Admin & Engineering:						\$ 624.80
TOTAL:						\$ 9,300.00


PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49A Avenue	Lot 33/34 Approach	E. Side	2669 - E06

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	6
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	1.5	%		
		Thickness	1.6mm		Length	10.47	m	

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.90

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	Yes
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert in poor condition. Approach is paved. Culvert end is deformed as dog is pointing out.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2669 - E06


Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	455.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	12	\$ 300.00	\$ 3,600.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	30	\$ 82.50	\$ 2,475.00
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 7,480.00
10% Contingencies:						\$ 748.00
8% Admin & Engineering:						\$ 598.40
TOTAL:						\$ 8,900.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49A Avenue	E. Side of Sunset Dr.	Centreline	2720 - E15

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	5
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	600	mm	
	Box		Steel	✓	Slope	-0.1	%	
		Thickness	1.6mm	Length	14.11	m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.75



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	Yes
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	Inadequate

Comments
Needs sloped ends with rip rap. Make longer 1m per end. No signs of capacity issues such as flowing over road. No ponding evident.



Inspected By: _____ D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2720 - E15

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	725.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 800mm C.S.P. Culvert	m	16	\$ 425.00	\$ 6,800.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	30	\$ 82.50	\$ 2,475.00
Sub-Total						\$ 10,450.00
10% Contingencies:						\$ 1,045.00
8% Admin & Engineering:						\$ 836.00
TOTAL:						\$ 12,400.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2721 - E16

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	275.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	6	\$ 300.00	\$ 1,800.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 3,025.00
10% Contingencies:						\$ 302.50
8% Admin & Engineering:						\$ 242.00
TOTAL:						\$ 3,600.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49A Avenue	S. Side, E. of Sunset Dr.	Multi-Use Trail	2722 - E03

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
	Box	

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	400	mm
Slope	0.9	%
Length	2.34	m

Overall Rating
6

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.00

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	Yes
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
Culvert in fair to good condition. Culvert alignment is poor to flow with ditch to the east.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2722 - E03

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	275.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	6	\$ 300.00	\$ 1,800.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 3,025.00
10% Contingencies:						\$ 302.50
8% Admin & Engineering:						\$ 242.00
TOTAL:						\$ 3,600.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49A Avenue	Lot 1/2 Approach	N. Side	2723 - E15

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	600	mm	
Box		Steel	✓	Slope	-0.1	%		
		Thickness	1.6mm	Length	14.11	m		

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.70

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	Yes
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	Negligible

Comments
Culvert in fair to poor condition. Approach is paved. Bent on the end.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2723 - E15

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	545.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	15	\$ 300.00	\$ 4,500.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	30	\$ 82.50	\$ 2,475.00
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 8,470.00
10% Contingencies:						\$ 847.00
8% Admin & Engineering:						\$ 677.60
TOTAL:						\$ 10,000.00

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49A Avenue	Lot 28/29 Approach	S. Side	2724 - E04

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	300	mm
Slope	3.6	%
Length	8.93	m

Overall Rating
6


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.30

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	Yes
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert in fair to poor condition. Approach is paved. Barely could see through.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2724 - E04

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	395.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	30	\$ 82.50	\$ 2,475.00
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 6,820.00
10% Contingencies:						\$ 682.00
8% Admin & Engineering:						\$ 545.60
TOTAL:						\$ 8,100.00

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2725 - E05

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	535.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	13	\$ 300.00	\$ 3,900.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 1,000.00	\$ 1,000.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	35	\$ 82.50	\$ 2,887.50
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 8,772.50
10% Contingencies:						\$ 877.25
8% Admin & Engineering:						\$ 701.80
TOTAL:						\$ 10,400.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49A Avenue	Lot 3/4 Approach	N. Side	2725b

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	3
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope		%		
		Thickness	1.6mm		Length	12?	m	


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.90

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	Yes
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	Negligible

Comments
Culvert in good to fair condition. Approach is not paved. Culvert end on the east was recently extended by 4m. Still old original culvert in the ground from the west.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: Saturday, February 15, 2020
Culvert: 2775b

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	485.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	13	\$ 300.00	\$ 3,900.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	35	\$ 40.00	\$ 1,400.00
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 6,735.00
10% Contingencies:						\$ 673.50
8% Admin & Engineering:						\$ 538.80
TOTAL:						\$ 8,000.00

EXISTING INFRASTRUCTURE REVIEW
SUMMER VILLAGE OF SUNSET POINT
FEBRUARY 2020

SE DESIGN AND CONSULTING INC.

ENGINEERS • CONSULTANTS • SURVEYORS

Sunset Drive Culvert Inspection Reports

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 1, 2019

PROJECT NAME:	2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	E. Backlane	N. Ditch	2201 - C02

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	8
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	-0.20	%		
		Thickness	1.6mm		Length	4.43	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
Small culvert that should be replaced with an 800mm Dia. CSP at minimum since area to the east is undeveloped and this drainage path will likely be increasing in flow.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2201-C02

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	357.50
2		Channel Excavation	m3	2	\$ 150.00	\$ 300.00
3		Remove & Dispose 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 800mm C.S.P. Culvert	m	7	\$ 425.00	\$ 2,975.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum		\$ 1,000.00	\$ -
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
8		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
9		Cleaning out of Culvert	lump sum		\$ 1,500.00	\$ -
Sub-Total						\$ 4,932.50
10% Contingencies:						\$ 493.25
8% Admin & Engineering:						\$ 394.60
TOTAL:						\$ 5,900.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	E. Backlane	N. Ditch, Multi-Use Trail	2201a - C02

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
		Arch		Aluminum		Span		mm
	Circular		Concrete		Rise		mm	
	Elliptical		Plastic		Diameter		mm	
	Box		Steel		Slope		%	
			Thickness		Length		m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
2 small culverts that should be replaced with an 800mm Dia. CSP at minimum since area to the east is undeveloped and this drainage path will likely be increasing in flow.

Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2201a-C02

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	315.00
2		Channel Excavation	m3	2	\$ 150.00	\$ 300.00
3		Remove & Dispose 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 800mm C.S.P. Culvert	m	6	\$ 425.00	\$ 2,550.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum		\$ 1,000.00	\$ -
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
8		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2		\$ 40.00	\$ -
9		Cleaning out of Culvert	lump sum		\$ 1,500.00	\$ -
					Sub-Total	\$ 3,465.00
					10% Contingencies:	\$ 346.50
					8% Admin & Engineering:	\$ 277.20
					TOTAL:	\$ 4,100.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	48th Avenue	Centreline	2202 - C01

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	7
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	600	mm	
Box		Steel	✓	Slope	2.30	%		
			Thickness	1.6mm	Length	22.81	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.75



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	Yes
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	MAJOR
Function of size, slope and condition	100-Year

Comments
 This crossing is for a Major Flow Path for an undeveloped area. The existing 600mm Dia. culvert maybe too small for future flow upstream. Needs sloped ends with rip rap. Make longer 1m per end. Potentially included **IN PROJECT #4. Could consider just adding 1 - 800mm Dia. CSP and leaving the existing 600mm Dia. CSP. Down drain open channel may require additional berm on the north side to ensure flow does not enter lot.**



Inspected By: D. Paulichuk, P. Eng.
 Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2202 - C01

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	1,410.00
2		Channel Excavation	m3	4	\$ 150.00	\$ 600.00
3		Supply & Install 800mm C.S.P. Culvert	m	3	\$ 425.00	\$ 1,275.00
4		Supply & Install 800mm C.S.P. Culvert	m	25	\$ 425.00	\$ 10,625.00
5		Supply & Install Rip Rap	unit	4	\$ 150.00	\$ 600.00
6		Light Grading	lump sum	1	\$ 1,000.00	\$ 1,000.00
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	48	\$ 82.50	\$ 3,960.00
Sub-Total						\$ 19,470.00
10% Contingencies:						\$ 1,947.00
8% Admin & Engineering:						\$ 1,557.60
TOTAL:						\$ 23,000.00

PROJECT NAME:	2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	E. of Sunset Drive	Drainage Way between Lot 1 & Lot 1	2203 - B05

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	12
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	500	mm	
Box		Steel	✓	Slope	0.70	%		
		Thickness	1.6mm		Length	52.76	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	Yes
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.60

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	Yes
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
 This culvert is very long with several issues. The inlet is within the road surface and presents a safety concern. Cannot verify if this culvert is plugged due to the length. There is significant siltation at the inlet end. The outlet end appears to be in good condition. Overall, it is appears that this culvert is not functioning as there is little evidence of flow from the outlet. Culvert should be unplugged immediately and lengthened on the inlet end. Needs rip rap. Recommend to replace with an 1 - 800mm Dia. CSP. or open channel. **PROJECT #4.**



**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2203-B05

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	2,767.50
2		Channel Excavation	m3	20	\$ 150.00	\$ 3,000.00
3		Remove & Dispose 800mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 800mm C.S.P. Culvert	m	55	\$ 425.00	\$ 23,375.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 1,000.00	\$ 1,000.00
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	10	\$ 82.50	\$ 825.00
8		Cleaning out of Culvert	lump sum		\$ 1,500.00	\$ -
Sub-Total						\$ 31,267.50
10% Contingencies:						\$ 3,126.75
8% Admin & Engineering:						\$ 2,501.40
TOTAL:						\$ 36,900.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	46th Ave. E. Service Rd	E. Side	2204 - B04

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	8
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	0.50	%		
		Thickness	1.6mm	Length	10.43	m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.65

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	Yes
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	Yes
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	Inadequate

Comments
Culvert appears to be in fair to good condition but undersized. Capacity is of concern now. When time to be replaced, replace with 800mm Dia. CSP with sloped ends with rip rap. **PROJECT #4.**



Inspected By: _____ D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2204 - B04

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	590.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 800mm C.S.P. Culvert	m	12	\$ 425.00	\$ 5,100.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
					Sub-Total	\$ 7,490.00
					10% Contingencies:	\$ 749.00
					8% Admin & Engineering:	\$ 599.20
					TOTAL:	\$ 8,900.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	46th Avenue (Park)	Centreline	2205 - B03

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	7
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	600	mm	
Box		Steel	✓	Slope	2.60	%		
			Thickness	1.6mm	Length	16.56	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.25

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	Yes
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	No
Corrosion / Abrasion	Yes
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking, Separation	Yes

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
This culvert is in fair to good condition. The existing 600mm Dia. culvert maybe too small for future flow upstream. Needs sloped ends with rip rap. Make longer 1m per end. Replace when aged out with an 1 - 800mm Dia. CSP. PROJECT #4.

Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2205- B03

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	925.00
2		Channel Excavation	m3	2	\$ 150.00	\$ 300.00
3		Supply & Install 800mm C.S.P. Culvert	m	18	\$ 425.00	\$ 7,650.00
4		Supply & Install 800mm C.S.P. Culvert	m		\$ 425.00	\$ -
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 1,000.00	\$ 1,000.00
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	35	\$ 82.50	\$ 2,887.50
Sub-Total						\$ 13,062.50
10% Contingencies:						\$ 1,306.25
8% Admin & Engineering:						\$ 1,045.00
TOTAL:						\$ 15,500.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2206-B01

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	425.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	8	\$ 350.00	\$ 2,800.00
4		Supply & Install 600mm C.S.P. Culvert	m		\$ 425.00	\$ -
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 1,000.00	\$ 1,000.00
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	35	\$ 82.50	\$ 2,887.50
8		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	20	\$ 40.00	\$ 800.00
Sub-Total						\$ 8,362.50
10% Contingencies:						\$ 836.25
8% Admin & Engineering:						\$ 669.00
TOTAL:						\$ 9,900.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	46th Avenue (Park)	Centreline	2207 - B02

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	5
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	0.90	%		
			Thickness	1.6mm	Length	5.38	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.30



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Needs Apron

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
 This culvert is in good condition. The existing 400mm Dia. culvert maybe too small for future flow upstream. Needs sloped ends with rip rap. Replace when aged out with an 1 - 600mm Dia. CSP.
PROJECT #4.



Inspected By: D. Paulichuk, P. Eng.
 Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2207-B02

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	425.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	8	\$ 350.00	\$ 2,800.00
4		Supply & Install 600mm C.S.P. Culvert	m		\$ 425.00	\$ -
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 1,000.00	\$ 1,000.00
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	35	\$ 82.50	\$ 2,887.50
8		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	20	\$ 40.00	\$ 800.00
Sub-Total						\$ 8,362.50
10% Contingencies:						\$ 836.25
8% Admin & Engineering:						\$ 669.00
TOTAL:						\$ 9,900.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 2 Approach	E. Side	2208 - B13

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	1.40	%		
			Thickness	1.6mm	Length	6.33	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.30

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	Needs Aprons



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2208- B13

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	320.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	8	\$ 300.00	\$ 2,400.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
					Sub-Total	\$ 4,520.00
					10% Contingencies:	\$ 452.00
					8% Admin & Engineering:	\$ 361.60
					TOTAL:	\$ 5,400.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 10 Approach	W. Side	2209 - B06

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	400	mm
Slope	1.00	%
Length	10.58	m

Overall Rating
3

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.60

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Needs Aprons



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2209 - B06

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	440.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	12	\$ 300.00	\$ 3,600.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 5,840.00
10% Contingencies:						\$ 584.00
8% Admin & Engineering:						\$ 467.20
TOTAL:						\$ 6,900.00

PROJECT NAME:	2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 8/9 Approach	W. Side	2210 - B07

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	6
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	1.10	%		
			Thickness	1.6mm	Length	16.29	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.20

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	Yes
Rip Rap	Needs Aprons




Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	Yes
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap. **Review slope of culvert as water is sitting within culvert. Also, the ditch could use some reshaping as there is very little backslope and this could allow flow to go into the lot.**



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2210 - B07

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	740.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	17	\$ 300.00	\$ 5,100.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 1,500.00	\$ 1,500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	40	\$ 40.00	\$ 1,600.00
					Sub-Total	\$ 9,740.00
					10% Contingencies:	\$ 974.00
					8% Admin & Engineering:	\$ 779.20
					TOTAL:	\$ 11,500.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 3/4 Approach	E. Side	2211 - B14

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	400	mm
Slope	3.60	%
Length	6.19	m

Overall Rating
3


Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.30

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Needs Aprons

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2211- B14

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	320.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	8	\$ 300.00	\$ 2,400.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
					Sub-Total	\$ 4,520.00
					10% Contingencies:	\$ 452.00
					8% Admin & Engineering:	\$ 361.60
					TOTAL:	\$ 5,400.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 7 Approach	W. Side	2212 - B08

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	400	mm
Slope	0.70	%
Length	11.45	m

Overall Rating
4

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.60

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	Needs Aprons



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2212 - B08

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	440.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	12	\$ 300.00	\$ 3,600.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	25	\$ 82.50	\$ 2,062.50
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2		\$ 40.00	\$ -
					Sub-Total	\$ 6,902.50
					10% Contingencies:	\$ 690.25
					8% Admin & Engineering:	\$ 552.20
					TOTAL:	\$ 8,200.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 4/5 Approach	E. Side	2213 - B15

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	400	mm
Slope	1.40	%
Length	10.35	m

Overall Rating
4

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.55

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	Needs Aprons



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2213- B15

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	440.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	12	\$ 300.00	\$ 3,600.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
					Sub-Total	\$ 5,840.00
					10% Contingencies:	\$ 584.00
					8% Admin & Engineering:	\$ 467.20
					TOTAL:	\$ 6,900.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 6 Approach	W. Side	2214 - B09

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	400	mm
Slope	1.80	%
Length	8.23	m

Overall Rating
3

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.60

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Needs Aprons



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2214 - B09

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	380.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	25	\$ 82.50	\$ 2,062.50
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2		\$ 40.00	\$ -
					Sub-Total	\$ 6,242.50
					10% Contingencies:	\$ 624.25
					8% Admin & Engineering:	\$ 499.40
					TOTAL:	\$ 7,400.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 5 Approach	W. Side	2215 - B10

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	3
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	0.50	%		
			Thickness	1.6mm	Length	8.33	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.30

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Needs Aprons



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2215 - B10

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	380.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	-
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	25	\$ 82.50	\$ 2,062.50
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2		\$ 40.00	\$ -
					Sub-Total	\$ 6,242.50
					10% Contingencies:	\$ 624.25
					8% Admin & Engineering:	\$ 499.40
					TOTAL:	\$ 7,400.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 6/7 Approach	E. Side	2216 - B16

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	400	mm
Slope	1.10	%
Length	10.36	m

Overall Rating
3

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.55

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Needs Aprons

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2216- B16

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	440.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	12	\$ 300.00	\$ 3,600.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
					Sub-Total	\$ 5,840.00
					10% Contingencies:	\$ 584.00
					8% Admin & Engineering:	\$ 467.20
					TOTAL:	\$ 6,900.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 3/4 Approach	W. Side	2217 - B11

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	3
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	0.70	%		
			Thickness	1.6mm	Length	8.24	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.30

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Needs Aprons

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2217 - B11

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	380.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	-
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	50	\$ 82.50	\$ 4,125.00
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2		\$ 40.00	\$ -
					Sub-Total	\$ 8,305.00
					10% Contingencies:	\$ 830.50
					8% Admin & Engineering:	\$ 664.40
					TOTAL:	\$ 9,800.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 2/3 Approach	W. Side	2218 - B12

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
	Box	

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	400	mm
Slope	0.70	%
Length	8.24	m

Overall Rating
3

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.30

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Needs Aprons



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2218- B12

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	380.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	30	\$ 40.00	\$ 1,200.00
					Sub-Total	\$ 5,380.00
					10% Contingencies:	\$ 538.00
					8% Admin & Engineering:	\$ 430.40
					TOTAL:	\$ 6,400.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 8/9 Approach	E. Side	2219 - B17

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	5
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	0.20	%		
			Thickness	1.6mm	Length	12.35	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.55

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Needs Aprons

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2219- B17

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	500.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	14	\$ 300.00	\$ 4,200.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
					Sub-Total	\$ 6,500.00
					10% Contingencies:	\$ 650.00
					8% Admin & Engineering:	\$ 520.00
					TOTAL:	\$ 7,700.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Backlane Approach	E. Side	2220 - B18

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	0.30	%		
			Thickness	1.6mm	Length	6.16	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.25

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Needs Aprons

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	10-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2220- B18

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	320.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	8	\$ 300.00	\$ 2,400.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	-
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	-
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
					Sub-Total	\$ 4,520.00
					10% Contingencies:	\$ 452.00
					8% Admin & Engineering:	\$ 361.60
					TOTAL:	\$ 5,400.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 6A Approach	W. Side	2221 - A24

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	3
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
	Box		Steel	✓	Slope	1.10	%	
		Thickness	1.6mm	Length	7.38	m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.30

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2221 - A24

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	350.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	-
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	-
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
					Sub-Total	\$ 4,850.00
					10% Contingencies:	\$ 485.00
					8% Admin & Engineering:	\$ 388.00
					TOTAL:	\$ 5,800.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot A Approach	E. Side	2222 - A26

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
	Box		Steel	✓	Slope	2.20	%	
		Thickness	1.6mm	Length	6.01	m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.35

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2222 - A26

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	320.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	8	\$ 300.00	\$ 2,400.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
					Sub-Total	\$ 4,520.00
					10% Contingencies:	\$ 452.00
					8% Admin & Engineering:	\$ 361.60
					TOTAL:	\$ 5,400.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 5 Approach	W. Side	2223 - A23

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	3
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	2.30	%		
			Thickness	1.6mm	Length	10.37	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.35

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2223 - A23

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	410.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	11	\$ 300.00	\$ 3,300.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	-
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	-
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
					Sub-Total	\$ 5,510.00
					10% Contingencies:	\$ 551.00
					8% Admin & Engineering:	\$ 440.80
					TOTAL:	\$ 6,600.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Backlane Approach	E. Side	2224 - A25

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	500	mm
Slope	0.50	%
Length	9.89	m

Overall Rating
3

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.35

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Missing some

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
Culvert appears to be in very good condition. Culvert is too small for 25-Year target capacity and should be replaced with an 800mm Dia. CSP with sloped ends and rip rap. Since the watermark in the culvert reveals a very low level, the need for improvement is not high priority and should be reviewed if there is new development upstream. Better slope within the culvert should also be improved.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2224 - A25

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	547.50
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 800mm C.S.P. Culvert	m	11	\$ 425.00	\$ 4,675.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	-
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	30	\$ 82.50	\$ 2,475.00
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2		\$ 40.00	\$ -
					Sub-Total	\$ 8,497.50
					10% Contingencies:	\$ 849.75
					8% Admin & Engineering:	\$ 679.80
					TOTAL:	\$ 10,100.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 2/3 Approach	W. Side	2235 - A22

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	3
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	-0.80	%		
			Thickness	1.6mm	Length	6.26	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.35

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2235 - A22

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	410.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	11	\$ 300.00	\$ 3,300.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	-
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	-
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
					Sub-Total	\$ 5,510.00
					10% Contingencies:	\$ 551.00
					8% Admin & Engineering:	\$ 440.80
					TOTAL:	\$ 6,600.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 2 Approach	W. Side	2236 - A21

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	400	mm
Slope	0.80	%
Length	9.91	m

Overall Rating
4

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.20

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	No apron

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	Yes
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap. Check slope in culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2236 - A21

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	380.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	-
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	-
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
					Sub-Total	\$ 5,180.00
					10% Contingencies:	\$ 518.00
					8% Admin & Engineering:	\$ 414.40
					TOTAL:	\$ 6,200.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date: November 4, 2019

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 1 Approach	W. Side	2237 - A20

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	0.40	%		
			Thickness	1.6mm	Length	11.31	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.20

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	No apron

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	Yes
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap. Check slope in culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2237 - A20

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	440.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	12	\$ 300.00	\$ 3,600.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	-
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	-
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
					Sub-Total	\$ 5,840.00
					10% Contingencies:	\$ 584.00
					8% Admin & Engineering:	\$ 467.20
					TOTAL:	\$ 6,900.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Boundary Rd. (42nd St.)	Centreline	2238 - A11

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	8
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	600	mm	
Box		Steel	✓	Slope	1.90	%		
			Thickness	1.6mm	Length	15.06	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.50



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	Yes
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	Yes
Submerged in Water	No
Inlet Damage	No
Outlet damage	Yes
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
This crossing is for a Minor Flow Path but collects 2 Minor Flow Paths including for an undeveloped area. The existing 600mm Dia. culvert maybe too small for future flow upstream. Recommend upgrading this crossing to an 800mm Dia. CSP to increase capacity needed with sloped ends and rip rap. Down drain open channel may require review to ensure flow does not enter lot and ensure protection from erosion.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2238 - A11

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	882.50
2		Channel Excavation	m3	2	\$ 150.00	\$ 300.00
3		Supply & Install 800mm C.S.P. Culvert	m	17	\$ 425.00	\$ 7,225.00
4		Supply & Install 800mm C.S.P. Culvert	m		\$ 425.00	-
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 1,000.00	\$ 1,000.00
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	48	\$ 82.50	\$ 3,960.00
Sub-Total						\$ 13,667.50
10% Contingencies:						\$ 1,366.75
8% Admin & Engineering:						\$ 1,093.40
TOTAL:						\$ 16,200.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	56 Avenue	Road E. Side	2602 - I06

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	7
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	600	mm	
Box		Steel	✓	Slope	0.90	%		
		Thickness	1.6mm		Length	12.79	m	

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.00

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	Partial
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
 Culvert is in fair to good condition. Need to clean out heavy grass at inlet and outlet. Widen out ditch. Re-check elevations as there is too much water being held within pipe which lowers capacity. Culvert needs sloped end on outlet side. Recommend once this culvert has aged and reached its design life, replace with one 800mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
 Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2602-106

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	690.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 800mm C.S.P. Culvert	m	14	\$ 425.00	\$ 5,950.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	30	\$ 82.50	\$ 2,475.00
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2		\$ 40.00	\$ -
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
Sub-Total						\$ 10,065.00
10% Contingencies:						\$ 1,006.50
8% Admin & Engineering:						\$ 805.20
TOTAL:						\$ 11,900.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	East Service Road	56th Ave. Approach	Under Service Rd.	2603 - I12

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	600	mm	
Box		Steel	✓	Slope	2.20	%		
		Thickness	1.6mm		Length	16.39	m	



Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.60

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert is in fair to good condition. Need to clean out heavy grass and tree at inlet and outlet. Widen out ditch. Culvert needs sloped end on outlet side. Recommend once this culvert has aged and reached its design life, replace with one 600mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 26103-112

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	725.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 600mm C.S.P. Culvert	m	18	\$ 350.00	\$ 6,300.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
Sub-Total						\$ 8,975.00
10% Contingencies:						\$ 897.50
8% Admin & Engineering:						\$ 718.00
TOTAL:						\$ 10,600.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2617 - I07

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	550.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 600mm C.S.P. Culvert	m	13	\$ 350.00	\$ 4,550.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
Sub-Total						\$ 7,050.00
10% Contingencies:						\$ 705.00
8% Admin & Engineering:						\$ 564.00
TOTAL:						\$ 8,400.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Service Rd./Backlane	Approach, E. Side	2619 - I11

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span		7
	Circular	✓	Concrete		Rise		
	Elliptical		Plastic		Diameter	300 mm	
Box		Steel	✓	Slope	1.00 %		
		Thickness	1.6mm	Length	10.25 m		


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.75

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	Inadequate

Comments
Culvert is in fair to good condition. but too small. Telephone cable is running inside culvert to pedestal. Need to clean out heavy grass at inlet and outlet. Widen out ditch. Culvert needs sloped end on outlet side. Recommend once this culvert has aged and reached its design life, replace with one 600mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2619 - I11

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	515.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 600mm C.S.P. Culvert	m	12	\$ 350.00	\$ 4,200.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	30	\$ 82.50	\$ 2,475.00
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2		\$ 40.00	\$ -
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
Sub-Total						\$ 8,140.00
10% Contingencies:						\$ 814.00
8% Admin & Engineering:						\$ 651.20
TOTAL:						\$ 9,700.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date: November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Service Rd. Approach	E. Side	2634 - H19

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete	✓	Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel		Slope	5.1	%		
		Thickness		Length	8.32	m		

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.35

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	Yes
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears in fair to good condition. Culvert too small. Should be replaced with a 500mm CSP minimum with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2634 - H19

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 395.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 5,345.00
10% Contingencies:						\$ 534.50
8% Admin & Engineering:						\$ 427.60
TOTAL:						\$ 6,400.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	54th Avenue	Centreline	2635 - H18

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	6
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	600	mm	
	Box		Steel	✓	Slope	0.20	%	
		Thickness	1.6mm	Length	15.18	m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.00

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	Yes
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	None



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	No
Corrosion / Abrasion	Some
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
 The high water mark can clearly be seen in this culvert which appears to be at 1/3 of the culvert capacity. Culvert is fair to good condition. Some rusting on the bottom. Should be upgraded to at least an 800mm Dia. CSP when time for this culvert to be replaced. If more development to occur upstream, this crossing should be reviewed in order to determine if this crossing is sufficient. Culvert should be longer with sloped ends and sideslopes should be flattened.



**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2635- H18

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	942.50
2		Channel Excavation	m3	4	\$ 150.00	\$ 600.00
3		Supply & Install 800mm C.S.P. Culvert	m	17	\$ 425.00	\$ 7,225.00
4		Supply & Install 800mm C.S.P. Culvert	m		\$ 425.00	\$ -
5		Supply & Install Rip Rap	unit	4	\$ 150.00	\$ 600.00
6		Light Grading	lump sum	1	\$ 1,000.00	\$ 1,000.00
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	48	\$ 82.50	\$ 3,960.00
Sub-Total						\$ 14,327.50
10% Contingencies:						\$ 1,432.75
8% Admin & Engineering:						\$ 1,146.20
TOTAL:						\$ 17,000.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Christian Camp Approach	W. Side	2644 - H17

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	10
	Circular	✓	Concrete	✓	Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel		Slope	1.9	%		
		Thickness		Length	28.51	m		

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.35

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	Could not see
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	????
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears in poor to fair condition. North end is buried and S. end is 3/4 full of water. Culvert too small. This is a very long culvert that could be plugged. Should be replaced with a 500mm CSP minimum with sloped ends and rip rap.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2644 - H17

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 995.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	30	\$ 300.00	\$ 9,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 11,945.00
10% Contingencies:						\$ 1,194.50
8% Admin & Engineering:						\$ 955.60
TOTAL:						\$ 14,100.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Christian Camp Approach	W. Side	2645 - H16

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	5
	Circular	✓	Concrete	✓	Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel		Slope	1.0	%		
		Thickness		Length	10.48	m		


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.00

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	Yes
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears in poor to fair condition. Culvert too small. Should be replaced with a 500mm CSP minimum with sloped ends and rip rap. Ditch should be widened out; excess vegetation removed.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2645 - H16


Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 455.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	12	\$ 300.00	\$ 3,600.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 6,005.00
10% Contingencies:						\$ 600.50
8% Admin & Engineering:						\$ 480.40
TOTAL:						\$ 7,100.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Christian Camp North	Centreline	2646 - H26

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	7
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	600	mm	
	Box		Steel	✓	Slope	1.80	%	
		Thickness	1.6mm	Length	15.54	m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.5 - 2.5



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	Yes
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	Some
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year



Comments
 The high water mark can clearly be seen in this culvert which is concerning and indicates that this culvert should be upgraded to at least an 800mm Dia. CSP when time for this culvert to be replaced. If more development to occur upstream, this crossing should be reviewed in order to determine if this crossing is sufficient. Culvert should be longer with sloped ends and sideslopes should be flattened. Ideally, 2 - 800mm Dia. CSPs should be installed.

Inspected By: D. Paulichuk, P. Eng.
 Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2646- H26

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	1,665.00
2		Channel Excavation	m3	4	\$ 150.00	\$ 600.00
3		Supply & Install 800mm C.S.P. Culvert	m	17	\$ 425.00	\$ 7,225.00
4		Supply & Install 800mm C.S.P. Culvert	m	17	\$ 425.00	\$ 7,225.00
5		Supply & Install Rip Rap	unit	4	\$ 150.00	\$ 600.00
6		Light Grading	lump sum	1	\$ 1,000.00	\$ 1,000.00
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	48	\$ 82.50	\$ 3,960.00
Sub-Total						\$ 22,275.00
10% Contingencies:						\$ 2,227.50
8% Admin & Engineering:						\$ 1,782.00
TOTAL:						\$ 26,300.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 8, 2019

PROJECT NAME:

2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Christian Camp Approach	W. Side	2647 - H15

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	10
	Circular	✓	Concrete	✓	Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
	Box		Steel		Slope	1.3	%	
		Thickness		Length	8.16	m		

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.00

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	Yes
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	Partial
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	Yes
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
Culvert appears in poor to fair condition. Culvert too small. Should be replaced with a 500mm CSP minimum with sloped ends and rip rap. Ditch should be widened out; excess vegetation removed.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2647 - H15

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 395.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 5,345.00
10% Contingencies:						\$ 534.50
8% Admin & Engineering:						\$ 427.60
TOTAL:						\$ 6,400.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2648 - H14

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 455.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	12	\$ 300.00	\$ 3,600.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 6,005.00
10% Contingencies:						\$ 600.50
8% Admin & Engineering:						\$ 480.40
TOTAL:						\$ 7,100.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Christian Camp Approach	W. Side	2649 - H13

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	10
	Circular	✓	Concrete	✓	Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel		Slope	1.2	%		
		Thickness		Length	8.35	m		

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.00

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	Inadequate

Comments
Appears to be concrete, therefore rusting not an issue. Condition is good but inside there appears to be separation. Approach is not paved. Partially silted. Culvert too small. Should be replaced with a 500mm CSP minimum with sloped ends and rip rap. Flatten out sideslopes to at least 5:1. Ditch should be widened out; excess vegetation removed.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2649 - H13

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 395.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 5,345.00
10% Contingencies:						\$ 534.50
8% Admin & Engineering:						\$ 427.60
TOTAL:						\$ 6,400.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Christian Camp Main Access	E. Side	2701 - H33

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	7
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	0.7	%		
		Thickness	1.6mm		Length	11.25	m	

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.65

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	Yes
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	Yes
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
Culvert in fair to poor condition. Approach is paved. Culvert too small. Should be replaced with a 500mm CSP minimum with sloped ends and rip rap. Flatten out sideslopes to at least 5:1. Excess vegetation removed.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2701 - H33

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 485.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	13	\$ 300.00	\$ 3,900.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	30	\$ 82.50	\$ 2,475.00
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 7,810.00
10% Contingencies:						\$ 781.00
8% Admin & Engineering:						\$ 624.80
TOTAL:						\$ 9,300.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2702 - H12

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 545.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	15	\$ 300.00	\$ 4,500.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	30	\$ 82.50	\$ 2,475.00
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 8,470.00
10% Contingencies:						\$ 847.00
8% Admin & Engineering:						\$ 677.60
TOTAL:						\$ 10,000.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Christian Camp South Access	E. Side	2703 - H32

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	7
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	0.7	%		
		Thickness	1.6mm		Length	6.46	m	

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.20

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	Inadequate



Comments
Culvert in fair to good condition. Approach is not paved. Culvert too small. Should be replaced with a 500mm CSP minimum with sloped ends and rip rap. Flatten out sideslopes to at least 5:1. Excess vegetation removed.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2703 - H32

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 335.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 500mm C.S.P. Culvert	m	8	\$ 300.00	\$ 2,400.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	30	\$ 40.00	\$ 1,200.00
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 4,885.00
10% Contingencies:						\$ 488.50
8% Admin & Engineering:						\$ 390.80
TOTAL:						\$ 5,800.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Christian Camp South Access	W. Side	2704 - H11

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	7
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	500	mm	
Box		Steel	✓	Slope	-0.8	%		
		Thickness	1.6mm		Length	10.42	m	

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.85

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	Yes
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
Culvert in fair to good condition. Approach is not paved. When comes time to be replaced, replace with a 600mm CSP minimum with sloped ends and rip rap. Flatten out sideslopes to at least 5:1. Excess vegetation removed.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2704 - H11


Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 515.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	12	\$ 350.00	\$ 4,200.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
8		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 6,665.00
10% Contingencies:						\$ 666.50
8% Admin & Engineering:						\$ 533.20
TOTAL:						\$ 7,900.00

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Christian Camp Mid South	Centreline	2705 - H01

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span		11
	Circular	✓	Concrete		Rise		
	Elliptical		Plastic		Diameter	600 mm	
	Box		Steel	✓	Slope	0.10 %	
		Thickness	1.6mm	Length	17.55 m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.5 - 2.5



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	Yes
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	No
Corrosion / Abrasion	Some
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	Inadequate

Comments
This crossing is for a Major Flow Path from the Christian Camp. The existing 600mm Dia. culvert is near capacity for a 25-Year Storm and it is recommended that it be upgraded to at least an 800mm Dia. CSP when time for this culvert to be replaced. If more development to occur upstream, this crossing should be reviewed in order to determine if this crossing is sufficient. Culvert should be longer with sloped ends and sideslopes should be flattened. Ideally, 2 - 800mm Dia. CSPs should be installed. Alignment should also be reviewed at the culvert alignment does not seem to align with drainage path on west side.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2705- H01

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	1,835.00
2		Channel Excavation	m3	4	\$ 150.00	\$ 600.00
3		Supply & Install 800mm C.S.P. Culvert	m	19	\$ 425.00	\$ 8,075.00
4		Supply & Install 800mm C.S.P. Culvert	m	19	\$ 425.00	\$ 8,075.00
5		Supply & Install Rip Rap	unit	4	\$ 150.00	\$ 600.00
6		Light Grading	lump sum	1	\$ 1,000.00	\$ 1,000.00
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	48	\$ 82.50	\$ 3,960.00
Sub-Total						\$ 24,145.00
10% Contingencies:						\$ 2,414.50
8% Admin & Engineering:						\$ 1,931.60
TOTAL:						\$ 28,500.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	E. of Sunset Dr.	Multi-Use Trail	2707- H02

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span		5
	Circular	✓	Concrete		Rise		
	Elliptical		Plastic		Diameter	600 mm	
Box		Steel	✓	Slope	2.0 %		
		Thickness	1.6mm		Length	7.9 m	


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.20

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	10-Year

Comments
This culvert will need to be replaced in conjunction with Culvert 2705, the centerline culvert under Sunset Drive. To match the centerline culvert, this culvert should be replaced with 2-800mm diameter CSPs.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2707 - H02

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 805.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 800mm C.S.P. Culvert	m	8	\$ 425.00	\$ 3,400.00
4		Supply & Install 800mm C.S.P. Culvert	m	8	\$ 425.00	\$ 3,400.00
5		Supply & Install Rip Rap	unit	4	\$ 150.00	\$ 600.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
8		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
9		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 8,855.00
10% Contingencies:						\$ 885.50
8% Admin & Engineering:						\$ 708.40
TOTAL:						\$ 10,500.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2708 - H03

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	385.00
2		Channel Excavation	m3	1	\$ 300.00	\$ 750.00
3		Supply & Install 600mm C.S.P. Culvert	m	8	\$ 350.00	\$ 2,800.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	30	\$ 40.00	\$ 1,200.00
Sub-Total						\$ 4,235.00
10% Contingencies:						\$ 423.50
8% Admin & Engineering:						\$ 338.80
TOTAL:						\$ 5,000.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2708a- G01

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	1,750.00
2		Channel Excavation	m3	4	\$ 150.00	\$ 600.00
3		Supply & Install 800mm C.S.P. Culvert	m	18	\$ 425.00	\$ 7,650.00
4		Supply & Install 800mm C.S.P. Culvert	m	18	\$ 425.00	\$ 7,650.00
5		Supply & Install Rip Rap	unit	4	\$ 150.00	\$ 600.00
6		Light Grading	lump sum	1	\$ 1,000.00	\$ 1,000.00
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	48	\$ 82.50	\$ 3,960.00
Sub-Total						\$ 23,210.00
10% Contingencies:						\$ 2,321.00
8% Admin & Engineering:						\$ 1,856.80
TOTAL:						\$ 27,400.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2708b - G02

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 550.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 800mm C.S.P. Culvert	m	5	\$ 425.00	\$ 2,125.00
4		Supply & Install 800mm C.S.P. Culvert	m	5	\$ 425.00	\$ 2,125.00
5		Supply & Install Rip Rap	unit	4	\$ 150.00	\$ 600.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
8		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
9		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 6,050.00
10% Contingencies:						\$ 605.00
8% Admin & Engineering:						\$ 484.00
TOTAL:						\$ 7,200.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	E. of Sunset Dr.	Multi-Use Trail	2712 - F02

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span		8
	Circular	✓	Concrete		Rise		
	Elliptical		Plastic		Diameter	600 mm	
Box		Steel	✓	Slope	1.2 %		
		Thickness	1.6mm		Length	3.45 m	


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.20

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	10-Year

Comments
This culvert will need to be replaced in conjunction with Culvert 2713, the centerline culvert under Sunset Drive. To match the centerline culvert, this culvert should be replaced with 2 800mm diameter CSPs.

Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2712 - F02

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 635.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 800mm C.S.P. Culvert	m	6	\$ 425.00	\$ 2,550.00
4		Supply & Install 800mm C.S.P. Culvert	m	6	\$ 425.00	\$ 2,550.00
5		Supply & Install Rip Rap	unit	4	\$ 150.00	\$ 600.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
8		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
9		Supply & Install 200mm Plastic Liner	m	0	\$ 300.00	\$ -
Sub-Total						\$ 6,985.00
10% Contingencies:						\$ 698.50
8% Admin & Engineering:						\$ 558.80
TOTAL:						\$ 8,300.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2713 - F01

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	1,750.00
2		Channel Excavation	m3	4	\$ 150.00	\$ 600.00
3		Supply & Install 800mm C.S.P. Culvert	m	18	\$ 425.00	\$ 7,650.00
4		Supply & Install 800mm C.S.P. Culvert	m	18	\$ 425.00	\$ 7,650.00
5		Supply & Install Rip Rap	unit	4	\$ 150.00	\$ 600.00
6		Light Grading	lump sum	1	\$ 1,000.00	\$ 1,000.00
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	48	\$ 82.50	\$ 3,960.00
Sub-Total						\$ 23,210.00
10% Contingencies:						\$ 2,321.00
8% Admin & Engineering:						\$ 1,856.80
TOTAL:						\$ 27,400.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2714- F32

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	360.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	9	\$ 350.00	\$ 3,150.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
Sub-Total						\$ 3,960.00
10% Contingencies:						\$ 396.00
8% Admin & Engineering:						\$ 316.80
TOTAL:						\$ 4,700.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2715-E14

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	745.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	20	\$ 350.00	\$ 7,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	36	\$ 82.50	\$ 2,970.00
Sub-Total						\$ 11,165.00
10% Contingencies:						\$ 1,116.50
8% Admin & Engineering:						\$ 893.20
TOTAL:						\$ 13,200.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2715a- E14a

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	-
2		Channel Excavation	m3	0	\$ 150.00	\$ -
3		Supply & Install 600mm C.S.P. Culvert	m	0	\$ 350.00	\$ -
4		Supply & Install Rip Rap	unit	0	\$ 150.00	\$ -
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
Sub-Total						\$ -
10% Contingencies:						\$ -
8% Admin & Engineering:						\$ -
TOTAL:						\$ -

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2716 - E13

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	315.00
2		Channel Excavation	m3	1	\$ 300.00	\$ 750.00
3		Supply & Install 600mm C.S.P. Culvert	m	6	\$ 350.00	\$ 2,100.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
Sub-Total						\$ 3,465.00
10% Contingencies:						\$ 346.50
8% Admin & Engineering:						\$ 277.20
TOTAL:						\$ 4,100.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2717 - E12

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	455.00
2		Channel Excavation	m3	1	\$ 300.00	\$ 750.00
3		Supply & Install 600mm C.S.P. Culvert	m	10	\$ 350.00	\$ 3,500.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
Sub-Total						\$ 5,005.00
10% Contingencies:						\$ 500.50
8% Admin & Engineering:						\$ 400.40
TOTAL:						\$ 6,000.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2718 - E11

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	455.00
2		Channel Excavation	m3	1	\$ 300.00	\$ 750.00
3		Supply & Install 600mm C.S.P. Culvert	m	10	\$ 350.00	\$ 3,500.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
Sub-Total						\$ 5,005.00
10% Contingencies:						\$ 500.50
8% Admin & Engineering:						\$ 400.40
TOTAL:						\$ 6,000.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2719 - E10

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	75.00
2		Channel Excavation	m3	1	\$ 300.00	\$ 750.00
3		Supply & Install 600mm C.S.P. Culvert	m	0	\$ 350.00	\$ -
4		Supply & Install Rip Rap	unit	0	\$ 150.00	\$ -
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
Sub-Total						\$ 825.00
10% Contingencies:						\$ 82.50
8% Admin & Engineering:						\$ 66.00
TOTAL:						\$ 1,000.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca


Date: September 27, 2019

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot Approach	W. Side	2726 - E09


Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	5
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
	Box		Steel	✓	Slope	0.10	%	
		Thickness	1.6mm	Length	8.26	m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.20



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
Small culvert that should be larger just to maintain flow and availability for cleaning out. Only other concern is the narrow V-Ditch which is a common problem along this drainage path. Since this drainage path is along the lake, recommend replacing with 600mm.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2726 - E09

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	395.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	10	\$ 350.00	\$ 3,500.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
Sub-Total						\$ 4,345.00
10% Contingencies:						\$ 434.50
8% Admin & Engineering:						\$ 347.60
TOTAL:						\$ 5,200.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2727 - E08

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	395.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 600mm C.S.P. Culvert	m	10	\$ 350.00	\$ 3,500.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
Sub-Total						\$ 4,345.00
10% Contingencies:						\$ 434.50
8% Admin & Engineering:						\$ 347.60
TOTAL:						\$ 5,200.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2728 - E01

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 895.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 800mm C.S.P. Culvert	m	20	\$ 425.00	\$ 8,500.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
Sub-Total						\$ 9,845.00
10% Contingencies:						\$ 984.50
8% Admin & Engineering:						\$ 787.60
TOTAL:						\$ 11,700.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2729 - E02

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	810.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Supply & Install 800mm C.S.P. Culvert	m	18	\$ 425.00	\$ 7,650.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	36	\$ 82.50	\$ 2,970.00
Sub-Total						\$ 11,880.00
10% Contingencies:						\$ 1,188.00
8% Admin & Engineering:						\$ 950.40
TOTAL:						\$ 14,100.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 8, 2019


PROJECT NAME:	2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lot 4A & 5 Approach	W. Side	2738 - D19

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	12
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	2.40	%		
		Thickness	1.6mm	Length	9.74	m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.55

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None



Pipe Barrel	Rating
Blockage	Yes
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	No
Corrosion / Abrasion	Yes
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be blocked or covered on one end. Small culvert that should be larger just to maintain flow and availability for cleaning out. Since this drainage path is along the lake, recommend replacing with 600mm.



Inspected By: _____ D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2738 - D19

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	500.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 600mm C.S.P. Culvert	m	12	\$ 350.00	\$ 4,200.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
Sub-Total						\$ 5,500.00
10% Contingencies:						\$ 550.00
8% Admin & Engineering:						\$ 440.00
TOTAL:						\$ 6,500.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2739 - D18

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	290.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 600mm C.S.P. Culvert	m	6	\$ 350.00	\$ 2,100.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 4,190.00
10% Contingencies:						\$ 419.00
8% Admin & Engineering:						\$ 335.20
TOTAL:						\$ 5,000.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2739a

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	430.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 600mm C.S.P. Culvert	m	10	\$ 350.00	\$ 3,500.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 5,730.00
10% Contingencies:						\$ 573.00
8% Admin & Engineering:						\$ 458.40
TOTAL:						\$ 6,800.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2740 - D02

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	547.50
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 800mm C.S.P. Culvert	m	11	\$ 425.00	\$ 4,675.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 7,022.50
10% Contingencies:						\$ 702.25
8% Admin & Engineering:						\$ 561.80
TOTAL:						\$ 8,300.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date: September 27, 2019

PROJECT NAME:	2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	48th Avenue	Centreline	2741 - D01

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	
Circular	✓	Concrete		Rise		mm		
Elliptical		Plastic		Diameter	600	mm		
Box		Steel	✓	Slope	1.30	%		
		Thickness	1.6mm	Length	23.54	m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.75



Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	Yes
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Major
Function of size, slope and condition	10-Year

Comments
This crossing is for a Major Flow Path for the subdivision in the 48th Street area. The existing 600mm Dia. culvert maybe too small and needs to be lowered by 0.7m at the inlet and 0.5m at the outlet in order to improvement flow upstream. Recommend 2 - 800mm Dia. CSPs since more flow may be directed this way in future. Needs sloped ends with rip rap. Make longer 1m per end. **INCLUDED IN PROJECT #1. Replacement is part of PROJECT #1 as a larger improvement project. Sideslopes should be flattened.**



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2741 - D01

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	2,345.00
2		Channel Excavation	m3	4	\$ 150.00	\$ 600.00
3		Supply & Install 800mm C.S.P. Culvert	m	25	\$ 425.00	\$ 10,625.00
4		Supply & Install 800mm C.S.P. Culvert	m	25	\$ 425.00	\$ 10,625.00
5		Supply & Install Rip Rap	unit	4	\$ 150.00	\$ 600.00
6		Light Grading	lump sum	1	\$ 1,000.00	\$ 1,000.00
7		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	48	\$ 82.50	\$ 3,960.00
Sub-Total						\$ 29,755.00
10% Contingencies:						\$ 2,975.50
8% Admin & Engineering:						\$ 2,380.40
TOTAL:						\$ 35,200.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2742 - D20

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	410.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	11	\$ 300.00	\$ 3,300.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 5,510.00
10% Contingencies						\$ 551.00
8% Admin & Engineering						\$ 440.80
TOTAL:						\$ 6,600.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2743 - C04

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	410.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	11	\$ 300.00	\$ 3,300.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 5,510.00
10% Contingencies						\$ 551.00
8% Admin & Engineering						\$ 440.80
TOTAL:						\$ 6,600.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 1, 2019


PROJECT NAME:	2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Sunset Drive	Lots 1 & 2	E. Side	2744 - C03

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	5
Circular	✓	Concrete		Rise		mm		
Elliptical		Plastic		Diameter	400	mm		
Box		Steel	✓	Slope	2.00	%		
		Thickness	1.6mm	Length	8.41	m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.50

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	None



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	Yes
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair to good condition but undersized. When time to be replaced, replace with 500mm Dia. CSP with sloped ends with rip rap.



Inspected By: _____ D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2744 - C03

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	380.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 5,180.00
10% Contingencies:						\$ 518.00
8% Admin & Engineering:						\$ 414.40
TOTAL:						\$ 6,200.00

EXISTING INFRASTRUCTURE REVIEW
SUMMER VILLAGE OF SUNSET POINT
FEBRUARY 2020

The logo for SE Design and Consulting Inc. features a blue rounded rectangle containing the company name in white, uppercase letters. This rectangle is positioned over a larger, solid yellow rectangle that has a white, curved cutout on its bottom-left corner.

SE DESIGN AND CONSULTING INC.

ENGINEERS • CONSULTANTS • SURVEYORS

54th Avenue and 49th Street Culvert Inspection Reports

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2620 - H25

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	315.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	0	\$ 500.00	\$ -
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	20	\$ 40.00	\$ 800.00
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
					Sub-Total	\$ 4,265.00
					10% Contingencies:	\$ 426.50
					8% Admin & Engineering:	\$ 341.20
					TOTAL:	\$ 5,100.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2621 - H24

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	315.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	0	\$ 500.00	\$ -
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	20	\$ 40.00	\$ 800.00
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
					Sub-Total	\$ 4,265.00
					10% Contingencies:	\$ 426.50
					8% Admin & Engineering:	\$ 341.20
					TOTAL:	\$ 5,100.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2622 - H20

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	315.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	0	\$ 500.00	\$ -
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	20	\$ 40.00	\$ 800.00
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
Sub-Total						\$ 4,265.00
10% Contingencies:						\$ 426.50
8% Admin & Engineering:						\$ 341.20
TOTAL:						\$ 5,100.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2623 - H21

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	420.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	13	\$ 300.00	\$ 3,900.00
5		Supply & Install Rip Rap	unit	1	\$ 150.00	\$ 150.00
6		Light Grading	lump sum	0	\$ 500.00	\$ -
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	20	\$ 40.00	\$ 800.00
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
					Sub-Total	\$ 5,420.00
					10% Contingencies:	\$ 542.00
					8% Admin & Engineering:	\$ 433.60
					TOTAL:	\$ 6,400.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49th Street Cul-de-Sac	Lot 17	Approach, S. Side	2624 - H22

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	5
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	3.2	%		
		Thickness	1.6mm		Length	7.57	m	


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.20

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert is in good condition. Inlet is near blocked and needs maintenance. Homemade opening between culverts should be replaced with proper catchbasin or drop inlet. Culvert needs sloped end on inlet side. Recommend once this culvert has aged and reached its design life, replace with one 500mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2624 - H22

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	320.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	8	\$ 300.00	\$ 2,400.00
5		Supply & Install Rip Rap	unit	1	\$ 150.00	\$ 150.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
10		Small Catchbasin/Drop Inlet	lump sum	1	\$ 2,500.00	\$ 2,500.00
					Sub-Total	\$ 7,020.00
					10% Contingencies:	\$ 702.00
					8% Admin & Engineering:	\$ 561.60
					TOTAL:	\$ 8,300.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2625 - H23

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	335.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	8	\$ 300.00	\$ 2,400.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 4,685.00
10% Contingencies:						\$ 468.50
8% Admin & Engineering:						\$ 374.80
TOTAL:						\$ 5,600.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2626 - H30

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	395.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 5,345.00
10% Contingencies:						\$ 534.50
8% Admin & Engineering:						\$ 427.60
TOTAL:						\$ 6,400.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2627 - I24

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	315.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	0	\$ 500.00	\$ -
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	20	\$ 40.00	\$ 800.00
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
					Sub-Total	\$ 4,265.00
					10% Contingencies:	\$ 426.50
					8% Admin & Engineering:	\$ 341.20
					TOTAL:	\$ 5,100.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49th Street Cul-de-Sac	Multi-Use Trail	Approach, N. Side	2628 - 124

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	3
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	400	mm	
Box		Steel	✓	Slope	4.90	%		
			Thickness	1.6mm	Length	2.88	m	

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.00

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert is in good condition. Culvert needs sloped ends. Recommend once this culvert has aged and reached its design life, replace with one 500mm diameter culvert.



Inspected By: _____ D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2628 - I20

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	195.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	5	\$ 300.00	\$ 1,500.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	0	\$ 500.00	\$ -
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
					Sub-Total	\$ 2,145.00
					10% Contingencies:	\$ 214.50
					8% Admin & Engineering:	\$ 171.60
					TOTAL:	\$ 2,600.00

Culvert Inspection Report

Date: November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49th Street Cul-de-Sac	Lot 23	Approach, NE. Side	2629 - I21

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	400	mm
Slope	2.00	%
Length	7.4	m

Overall Rating
5

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.35

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	???
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Cannot see through. Maybe be blocked. Culvert is in good condition. Culvert needs sloped end on outlet side. Recommend once this culvert has aged and reached its design life, replace with one 500mm diameter culvert.



Inspected By: _____ D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2629 - I21

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	315.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	0	\$ 500.00	\$ -
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	0	\$ 40.00	\$ -
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
Sub-Total						\$ 3,465.00
10% Contingencies:						\$ 346.50
8% Admin & Engineering:						\$ 277.20
TOTAL:						\$ 4,100.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 8, 2019

PROJECT NAME:

2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49th Street Cul-de-Sac	Lot 24	Approach, E. Side	2630 - 122

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	400	mm
Slope	2.30	%
Length	7.4	m

Overall Rating
3

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.50

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert is in fair condition. Culvert needs sloped end on outlet side. Recommend once this culvert has aged and reached its design life, replace with one 500mm diameter culvert.



Inspected By: _____ D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2630 - I22

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	315.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	0	\$ 500.00	\$ -
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
					Sub-Total	\$ 4,465.00
					10% Contingencies:	\$ 446.50
					8% Admin & Engineering:	\$ 357.20
					TOTAL:	\$ 5,300.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49th Street Cul-de-Sac	Lot 25	Approach, E. Side	2631 - I23

Pipe Details:	Shape (Select One)	
	Arch	
	Circular	✓
	Elliptical	
Box		

Material (Select One)	
Aluminum	
Concrete	
Plastic	
Steel	✓
Thickness	1.6mm

Pipe Size		
Span		mm
Rise		mm
Diameter	400	mm
Slope	1.40	%
Length	7.39	m

Overall Rating
4

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.40

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	Yes
Rip Rap	None



Pipe Barrel	Rating
Blockage	No
Submerged in Water	Partial
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert is in fair condition. Inlet and Outlet areas need to be cleared out so water flows better and does not sit inside culvert. Culvert needs sloped end on outlet side. Recommend once this culvert has aged and reached its design life, replace with one 500mm diameter culvert.



Inspected By: _____ D. Paulichuk, P. Eng. _____
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2631 - I23

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	315.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	0	\$ 500.00	\$ -
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
					Sub-Total	\$ 4,465.00
					10% Contingencies:	\$ 446.50
					8% Admin & Engineering:	\$ 357.20
					TOTAL:	\$ 5,300.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2619 - I11

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	365.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
					Sub-Total	\$ 5,015.00
					10% Contingencies:	\$ 501.50
					8% Admin & Engineering:	\$ 401.20
					TOTAL:	\$ 6,000.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2633 - H29

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	335.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	8	\$ 300.00	\$ 2,400.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 4,685.00
10% Contingencies:						\$ 468.50
8% Admin & Engineering:						\$ 374.80
TOTAL:						\$ 5,600.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2636 - H27

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	335.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	8	\$ 300.00	\$ 2,400.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 4,685.00
10% Contingencies:						\$ 468.50
8% Admin & Engineering:						\$ 374.80
TOTAL:						\$ 5,600.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2637 - H28

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	395.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	20	\$ 40.00	\$ 800.00
					Sub-Total	\$ 5,145.00
					10% Contingencies:	\$ 514.50
					8% Admin & Engineering:	\$ 411.60
					TOTAL:	\$ 6,100.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2637 - H28

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	365.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	25	\$ 82.50	\$ 2,062.50
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2		\$ 40.00	\$ -
					Sub-Total	\$ 6,077.50
					10% Contingencies:	\$ 607.75
					8% Admin & Engineering:	\$ 486.20
					TOTAL:	\$ 7,200.00

EXISTING INFRASTRUCTURE REVIEW
SUMMER VILLAGE OF SUNSET POINT
FEBRUARY 2020

SE DESIGN AND CONSULTING INC.

ENGINEERS • CONSULTANTS • SURVEYORS

56th Avenue and 49th Street Culvert Inspection Reports

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2605- 103

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 550.00
2		Channel Excavation	m3		\$ 2,000.00	\$ -
3		Remove & Salvage 400mm C.S.P. Culvert	m	110	\$ 50.00	\$ 5,500.00
4		Supply & Install 800mm C.S.P. Culvert	m		\$ 425.00	\$ -
5		Supply & Install Rip Rap	unit		\$ 150.00	\$ -
6		Light Grading	lump sum		\$ 500.00	\$ -
7		Re-Grade Ditch	lump sum		\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2		\$ 40.00	\$ -
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
					Sub-Total	\$ 6,050.00
					10% Contingencies:	\$ 605.00
					8% Admin & Engineering:	\$ 484.00
					TOTAL:	\$ 7,200.00

Culvert Inspection Report

Date: November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	56th Avenue	Parallel to 56th Ave.	N. Side Ditch	2605 - I03

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span		9
	Circular	✓	Concrete		Rise		
	Elliptical		Plastic		Diameter	400 mm	
Box		Steel	✓	Slope	0.80 %		
		Thickness	1.6mm		Length	105.08 m	


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.50

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	No
Corrosion / Abrasion	Yes
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	MAJOR
Function of size, slope and condition	5-Year

Comments
Culvert is in fair condition but small in size. INCLUDED IN PROJECT #3. Project # 3 indicates replacing this culvert with an 800mm Dia. CSP with sloped ends.


 Inspected By: D. Paulichuk, P. Eng.
 Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2605- 103

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	5,485.00
2		Channel Excavation	m3	1	\$ 2,000.00	\$ 2,000.00
3		Remove & Salvage 400mm C.S.P. Culvert	m	106	\$ 50.00	\$ 5,300.00
4		Supply & Install 800mm C.S.P. Culvert	m	110	\$ 425.00	\$ 46,750.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	1	\$ 2,000.00	\$ 2,000.00
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2		\$ 40.00	\$ -
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
Sub-Total						\$ 62,335.00
10% Contingencies:						\$ 6,233.50
8% Admin & Engineering:						\$ 4,986.80
TOTAL:						\$ 73,600.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 8, 2019

PROJECT NAME:	2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan
----------------------	---

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	56th Avenue	N. of Lot 21	Centerline	2606 - 104

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	8
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	600	mm	
Box		Steel	✓	Slope	2.60	%		
		Thickness	1.6mm		Length	14.18	m	


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.20

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	Yes
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	MAJOR
Function of size, slope and condition	100-Year

Comments
Culvert is in good condition. Water marks inside culvert indicates that flow is very low and not a large concern. Need to review sizing if development occurs upstream. Culvert needs sloped end on outlet side. Recommend once this culvert has aged and reached its design life, replace with one 800mm diameter culvert. **INCLUDED IN PROJECT #3. Project # 3 indicates leaving this culvert in place, just add sloped ends. New culvert to be placed in parallel.**



Inspected By: _____ D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2606- 104

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	220.00
2		Channel Excavation	m3		\$ 150.00	\$ -
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 600mm C.S.P. Culvert	m	4	\$ 350.00	\$ 1,400.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum		\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2		\$ 40.00	\$ -
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
Sub-Total						\$ 2,420.00
10% Contingencies:						\$ 242.00
8% Admin & Engineering:						\$ 193.60
TOTAL:						\$ 2,900.00

Culvert Inspection Report

Date: November 8, 2019


PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	56th Avenue	Backlane	Approach, S. Side	2607 - I13

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span	mm	
	Circular	✓	Concrete		Rise	mm	
	Elliptical		Plastic		Diameter	400 mm	
Box		Steel	✓	Slope	3.3 %	5	
		Thickness	1.6mm	Length	7.01 m		

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.30

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	Yes



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert is in fair to good condition. Culverts need sloped ends. Recommend once this culvert has aged and reached its design life, replace with one 600mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2607 - H13

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 410.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 600mm C.S.P. Culvert	m	9	\$ 350.00	\$ 3,150.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 5,510.00
10% Contingencies:						\$ 551.00
8% Admin & Engineering:						\$ 440.80
TOTAL:						\$ 6,600.00

Culvert Inspection Report

Date: November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	56th Avenue	Lot 7	Approach, S. Side	2608 - I14

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span		3
	Circular	✓	Concrete		Rise		
	Elliptical		Plastic		Diameter	600 mm	
Box		Steel	✓	Slope	1.2 %		
		Thickness	1.6mm		Length	7.67 m	


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.75

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	Yes

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert is in fair to good condition. Culverts need sloped ends. Recommend once this culvert has aged and reached its design life, replace with one 600mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2608 - I14

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 410.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 600mm C.S.P. Culvert	m	9	\$ 350.00	\$ 3,150.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 5,510.00
10% Contingencies:						\$ 551.00
8% Admin & Engineering:						\$ 440.80
TOTAL:						\$ 6,600.00

Culvert Inspection Report

Date: November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	56th Avenue	Lot 8	Approach, S. Side	2609 - I15

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span		4
	Circular	✓	Concrete		Rise		
	Elliptical		Plastic		Diameter	400 mm	
Box		Steel	✓	Slope	1.6 %		
		Thickness	1.6mm		Length	7.57 m	


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.55

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	Yes

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert is in fair to good condition. Culverts need sloped ends. Recommend once this culvert has aged and reached its design life, replace with one 500mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2609 - I15

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 365.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 5,015.00
10% Contingencies:						\$ 501.50
8% Admin & Engineering:						\$ 401.20
TOTAL:						\$ 6,000.00

Culvert Inspection Report

Date: November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	56th Avenue	Lot 9	Approach, S. Side	2610 - I16

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span	mm	4
	Circular	✓	Concrete		Rise	mm	
	Elliptical		Plastic		Diameter	400 mm	
Box		Steel	✓	Slope	0.5 %		
		Thickness	1.6mm		Length	7.59 m	


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.70

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	Yes

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert is in fair to good condition. Culverts need sloped ends. Recommend once this culvert has aged and reached its design life, replace with one 500mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2610 - I16

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 365.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 5,015.00
10% Contingencies:						\$ 501.50
8% Admin & Engineering:						\$ 401.20
TOTAL:						\$ 6,000.00

Culvert Inspection Report

Date: November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	56th Avenue	N. of Lot 21	S. Ditch of Turnaround	2611 - I05

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span	mm	
	Circular	✓	Concrete		Rise	mm	
	Elliptical		Plastic		Diameter	500 mm	
Box		Steel	✓	Slope	1.20 %	8	
		Thickness	1.6mm	Length	8.3 m		


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.20

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	Yes
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	MAJOR
Function of size, slope and condition	5-Year

Comments
Culvert is in fair to good condition. Water marks inside culvert indicates that flow goes only 1/3 up, so capacity not a large concern. Need to review sizing if development occurs upstream. Culvert needs sloped end on outlet side. INCLUDED IN PROJECT #3. Project # 3 indicates replacing this culvert. Consideration should be to leave in place, just add sloped ends. New culvert to be placed in parallel.

Inspected By: _____
D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2611- I05

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 265.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 800mm C.S.P. Culvert	m	4	\$ 425.00	\$ 1,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	1	\$ 2,000.00	\$ 2,000.00
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2		\$ 40.00	\$ -
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
						Sub-Total \$ 4,915.00
						10% Contingencies: \$ 491.50
						8% Admin & Engineering: \$ 393.20
						TOTAL: \$ 5,800.00

Culvert Inspection Report

Date: November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49th Street	Lot 21	Approach, SE. Side	2612 - I18

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span		5
	Circular	✓	Concrete		Rise		
	Elliptical		Plastic		Diameter	300	
Box		Steel	✓	Slope	1.9		
		Thickness	1.6mm		7.49		


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.50

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	Yes

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert is in fair to good condition. Culverts need sloped ends. Recommend once this culvert has aged and reached its design life, replace with one 500mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2612 - I18

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 365.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
						Sub-Total \$ 5,015.00
						10% Contingencies: \$ 501.50
						8% Admin & Engineering: \$ 401.20
						TOTAL: \$ 6,000.00

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49th Street	Lot 20	Approach, SE. Side	2612b

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span	mm	
	Circular		Concrete		Rise	mm	
	Elliptical		Plastic		Diameter	mm	
Box		Steel		Slope	%	7	
		Thickness		Length	m		


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	No

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
 No culvert at this approach to the lot. Drainage appears to flow through and over driveway and head toward buildings.
 Recommend that a 500mm Dia. CSP with sloped ends be installed under the approach to ensure drainage head down along the ditch to the north.



Inspected By: D. Paulichuk, P. Eng.
 Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2612b

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 365.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	1	\$ 1,000.00	\$ 1,000.00
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
						Sub-Total \$ 6,015.00
						10% Contingencies: \$ 601.50
						8% Admin & Engineering: \$ 481.20
						TOTAL: \$ 7,100.00

Culvert Inspection Report

Date: November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49th Street	Lot 10	Approach, W. Side	2613 - I17

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span		5
	Circular	✓	Concrete		Rise		
	Elliptical		Plastic		Diameter	400 mm	
Box		Steel	✓	Slope	1.9 %		
		Thickness	1.6mm		Length	7.25 m	


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.30

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	Yes

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	Yes
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert is in fair to good condition. Culverts need sloped ends. Recommend once this culvert has aged and reached its design life, replace with one 500mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2613 - 117

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 365.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
						Sub-Total \$ 5,015.00
						10% Contingencies: \$ 501.50
						8% Admin & Engineering: \$ 401.20
						TOTAL: \$ 6,000.00

Culvert Inspection Report

Date: November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49th Street Cul-de-Sac	Lot 16	Approach, S. Side	2614 - I19

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span		4
	Circular	✓	Concrete		Rise		
	Elliptical		Plastic		Diameter	400 mm	
Box		Steel	✓	Slope	2.9 %		
		Thickness	1.6mm		Length	7.00 m	

Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.50

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	Yes

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
Culvert is in fair to good condition. Culverts need sloped ends. Recommend once this culvert has aged and reached its design life, replace with one 500mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2614 - I19

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 365.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 5,015.00
10% Contingencies:						\$ 501.50
8% Admin & Engineering:						\$ 401.20
TOTAL:						\$ 6,000.00

Culvert Inspection Report

Date: November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49th Street Cul-de-Sac	Lot 15/16	Approach, S. Side	2614b

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating 7
	Arch		Aluminum		Span	mm	
	Circular		Concrete		Rise	mm	
	Elliptical		Plastic		Diameter	mm	
Box		Steel		Slope	%		
		Thickness		Length	m		


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	No

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
No culvert at this approach to the lot. Drainage appears to not flow past this point. Recommend that a 500mm Dia. CSP with sloped ends be installed under the approach to ensure drainage head down along the ditch to the west.

Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2614b

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 365.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	1	\$ 1,000.00	\$ 1,000.00
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	
						Sub-Total \$ 5,015.00
						10% Contingencies: \$ 501.50
						8% Admin & Engineering: \$ 401.20
						TOTAL: \$ 6,000.00

Culvert Inspection Report

Date: November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49th Street Cul-de-Sac	Lot 15	Approach, S. Side	2615 - I10

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span	mm	
	Circular	✓	Concrete		Rise	mm	
	Elliptical		Plastic		Diameter	200 mm	
Box		Steel	✓	Slope	5.5 %	7	
		Thickness	1.6mm	Length	6.14 m		


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.50

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	Yes

Pipe Barrel	Rating
Blockage	Partial
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
 Can't see fully through culvert. Culvert is in fair to good condition. Culverts need sloped ends. Recommend once this culvert has aged and reached its design life, replace with one 500mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
 Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2615 - I10

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 365.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
						Sub-Total \$ 5,015.00
						10% Contingencies: \$ 501.50
						8% Admin & Engineering: \$ 401.20
						TOTAL: \$ 6,000.00

Culvert Inspection Report

Date: November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	49th Street Cul-de-Sac	Lot 14	Approach, SW. Side	2616 - I09

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating
	Arch		Aluminum		Span		4
	Circular	✓	Concrete		Rise		
	Elliptical		Plastic		Diameter	400 mm	
Box		Steel	✓	Slope	7.1 %		
		Thickness	1.6mm		Length	7.58 m	


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.50

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	Yes
Silt	No
Rip Rap	Yes

Pipe Barrel	Rating
Blockage	Partial
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100 Year

Comments
 Can't see fully through culvert. Culvert is in fair to good condition. Culverts need sloped ends. Recommend once this culvert has aged and reached its design life, replace with one 500mm diameter culvert.



Inspected By: D. Paulichuk, P. Eng.
 Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2616 - I09

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum			\$ 365.00
2		Channel Excavation	m3	1	\$ 150.00	\$ 150.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum	0	\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2	0	\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 5,015.00
10% Contingencies:						\$ 501.50
8% Admin & Engineering:						\$ 401.20
TOTAL:						\$ 6,000.00

Culvert Inspection Report

Date: November 8, 2019

PROJECT NAME: 2020 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Back Lane	Between Service Rd. & Cul-de-Sac	Centerline	2618 - I08

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size		Overall Rating 14
	Arch		Aluminum		Span	mm	
	Circular	✓	Concrete		Rise	mm	
	Elliptical		Plastic		Diameter	400 mm	
	Box		Steel	✓	Slope	0.50 %	
		Thickness	1.6mm	Length	7.73 m		


Roadway Over Pipe	Response
Pavement Cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	1.20

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	Yes
Vegetation - trees, brush etc.	Yes
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	Yes
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	Yes
Corrosion / Abrasion	No
Out of Round	Yes
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	Inadequate

Comments
Culvert is in poor condition, is too small and appears to be partially blocked. Need to clean out trees and heavy grass at inlet and outlet. Culvert needs sloped end on outlet side. Recommend to replace with 600mm diameter culvert.

Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2618 - I08

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	545.00
2		Channel Excavation	m3	1	\$ 1,500.00	\$ 1,500.00
3		Remove & Salvage 500mm C.S.P. Culvert	m		\$ 100.00	\$ -
4		Supply & Install 600mm C.S.P. Culvert	m	9	\$ 350.00	\$ 3,150.00
5		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
6		Light Grading	lump sum	1	\$ 500.00	\$ 500.00
7		Re-Grade Ditch	lump sum		\$ 2,000.00	\$ -
8		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
9		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	30	\$ 40.00	\$ 1,200.00
10		Small Catchbasin/Drop Inlet	lump sum		\$ 2,500.00	\$ -
Sub-Total						\$ 7,195.00
10% Contingencies:						\$ 719.50
8% Admin & Engineering:						\$ 575.60
TOTAL:						\$ 8,500.00

EXISTING INFRASTRUCTURE REVIEW
SUMMER VILLAGE OF SUNSET POINT
FEBRUARY 2020



SE DESIGN AND CONSULTING INC.

ENGINEERS • CONSULTANTS • SURVEYORS

Boundary Road Culvert Inspection Reports

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 4, 2019


PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Boundary Road	Backlane	N. Side	2226 - A19

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	9
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	2.50	%		
		Thickness	1.6mm	Length	10.1	m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.20

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None



Pipe Barrel	Rating
Blockage	????
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	Yes
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap. Check slope in culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2226 - A19

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	380.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	10	\$ 300.00	\$ 3,000.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 5,180.00
10% Contingencies:						\$ 518.00
8% Admin & Engineering:						\$ 414.40
TOTAL:						\$ 6,200.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 4, 2019


PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Boundary Road	Lot 8 Approach	N. Side	2227 - A18

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	5
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	2.80	%		
		Thickness	1.6mm	Length		6.03	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.40

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	10-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap. Check slope in culvert.



Inspected By: _____ D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2227 - A18

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	320.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	8	\$ 300.00	\$ 2,400.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 4,520.00
10% Contingencies:						\$ 452.00
8% Admin & Engineering:						\$ 361.60
TOTAL:						\$ 5,400.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 4, 2019


PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Boundary Road	Lot 7 Approach	N. Side	2228 - A17

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	6.10	%		
			Thickness	1.6mm	Length	7.94	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.40

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	100-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap. Check slope in culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2228 - A17

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	350.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	9	\$ 300.00	\$ 2,700.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 4,850.00
10% Contingencies						\$ 485.00
8% Admin & Engineering						\$ 388.00
TOTAL:						\$ 5,800.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 4, 2019

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Boundary Road	Lot 6 Approach	N. Side	2232 - A16

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	7
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	1.60	%		
			Thickness	1.6mm	Length	6.31	m	


Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.35

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None

Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	Yes
Outlet damage	Yes
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No

Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	5-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap. Check slope in culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2232 - A16

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	320.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	8	\$ 300.00	\$ 2,400.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 4,520.00
10% Contingencies						\$ 452.00
8% Admin & Engineering						\$ 361.60
TOTAL:						\$ 5,400.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date: November 4, 2019

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Boundary Road	Lot 5 Approach	N. Side	2233 - A15

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	5
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	2.10	%		
			Thickness	1.6mm	Length	6.22	m	

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.35

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	Yes
Rip Rap	None



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	10-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap. Check slope in culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2233 - A15

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	320.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	8	\$ 300.00	\$ 2,400.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 4,520.00
10% Contingencies						\$ 452.00
8% Admin & Engineering						\$ 361.60
TOTAL:						\$ 5,400.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 4, 2019


PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Boundary Road	Lot 4 Approach	N. Side	2234 - A14

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	1.90	%		
		Thickness	1.6mm	Length	6.3	m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.35

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	10-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap. Check slope in culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2234 - A14

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	320.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	8	\$ 300.00	\$ 2,400.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 4,520.00
10% Contingencies						\$ 452.00
8% Admin & Engineering						\$ 361.60
TOTAL:						\$ 5,400.00

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2239 - A12

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	320.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	8	\$ 300.00	\$ 2,400.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 4,520.00
10% Contingencies:						\$ 452.00
8% Admin & Engineering:						\$ 361.60
TOTAL:						\$ 5,400.00

Culvert Inspection Report

SE DESIGN AND CONSULTING INC.

713 LAKESHORE DRIVE
COLD LAKE, ALBERTA
T9M 0C4

Phone: 780-594-5380
Fax: 780-594-4486
Web: www.sedesign.ca

Date:

November 4, 2019

PROJECT NAME: 2019 S.V. of Sunset Point Storm Water Management Plan & Rehabilitation Plan

Location:	City/County/MD	Road Name/No.	Station Number	Alignment	Culvert No./Name
	S.V. of Sunset Point	Boundary Road	Lot 3 Approach	N. Side	2240 - A13

Pipe Details:	Shape (Select One)		Material (Select One)		Pipe Size			Overall Rating
	Arch		Aluminum		Span		mm	4
	Circular	✓	Concrete		Rise		mm	
	Elliptical		Plastic		Diameter	300	mm	
Box		Steel	✓	Slope	1.70	%		
		Thickness	1.6mm	Length	6.41	m		

Roadway Over Pipe	Response
Pavement cracks or Patches	No
Sag in Roadway	No
Recent signs of high water	No
Amount of Cover (m)	0.35

Inlet / Outlet Protection	Rating
Channel scour at Inlet/Outlet	No
Embankment Erosion	No
Sideslopes too Steep	No
Drift - wood, debris around pipe	No
Vegetation - trees, brush etc.	No
Silt	No
Rip Rap	None



Pipe Barrel	Rating
Blockage	No
Submerged in Water	No
Inlet Damage	No
Outlet damage	No
Corrosion / Abrasion	No
Out of Round	No
Settlement	No
Sag / Bow	No
Infiltration	No
Piping	No
Cracking	No



Capacity	Rating
Flow Path Type	Minor
Function of size, slope and condition	10-Year

Comments
Culvert appears to be in fair to good condition. Small culvert that should be larger just to maintain flow and availability for cleaning out. Recommend when comes time for replacement, replace with 500mm Dia. CSP with sloped ends and rip rap. Check slope in culvert.



Inspected By: D. Paulichuk, P. Eng.
Name

**Culvert Improvement
Cost Estimate**Date: February 15, 2020
Culvert: 2240 - A13

Item	Spec. No.	Description	Unit	Quantity	Unit Price	Cost
1		Mobilization - 10%	lump sum		\$	320.00
2		Channel Excavation	m3	1	\$ 500.00	\$ 500.00
3		Supply & Install 500mm C.S.P. Culvert	m	8	\$ 300.00	\$ 2,400.00
4		Supply & Install Rip Rap	unit	2	\$ 150.00	\$ 300.00
5		Light Grading	lump sum	0	\$ 1,000.00	\$ -
6		Re-Pave Excavation Area - 2m x length (\$165/m) (\$82.50/m2 with 100mm ACP & 300mm GBC)	m2		\$ 82.50	\$ -
7		Re-Gravel Approach - 10m x 10m x 150mm x 2.33 (\$40.00/tonne GBC)	m2	25	\$ 40.00	\$ 1,000.00
Sub-Total						\$ 4,520.00
10% Contingencies						\$ 452.00
8% Admin & Engineering						\$ 361.60
TOTAL:						\$ 5,400.00